

102272

BOOK 6/5 PAGE 7

State of Washington  
DEPARTMENT OF NATURAL RESOURCES  
BUREAU OF SURVEYS AND MAPS  
**LAND CORNER RECORD**

21	22
28	27

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. R-13

Segregated Surveys:

Name: n/a

Corner Number: n/a

**1. History of Corner Establishment and Subsequent Restoration:**

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 bearing trees.

No subsequent restoration found.

FILED FOR RECORD  
SKAMANIA CO. WASH  
BY

**2. Description of Evidence Found:**

GLO stone with proper notches.  
32" T. fir stub at N21E 84 feet with overgrown face.  
66" cedar S63E 45 feet with visible scribe.  
48" T. fir at S52W 92 feet with overgrowth.  
Decayed fir stub, 1 foot high, at N65W 102 feet.

DEC 1 17 PM '86

AUDITOR  
GARY H. OLSON

**3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.**  
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 49. Date of work June 30, 1986.

Corner is the original andesite stone.

See reverse side for corner diagram.

**SURVEYOR'S CERTIFICATE**

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.  
Date: November 19, 1986.

H. Thomas Laird Jr.  
Signature

21490  
Certificate No.

**AUDITOR'S CERTIFICATE**

Filed for record this \_\_\_\_\_ day of \_\_\_\_\_ 19\_\_\_\_ at \_\_\_\_\_ M.  
In Book \_\_\_\_\_ of \_\_\_\_\_ at page \_\_\_\_\_ at the request  
of Washington State Department of Natural Resources.

Registered \_\_\_\_\_  
Indexed, Dir \_\_\_\_\_  
1 \_\_\_\_\_  
2 \_\_\_\_\_

County Auditor

Gordon  
Hawlin  
Miss Phares 602.07

6-30-81

Survey of 1909 (Pineda)  
 100 yd. SET BACK 12 WIDE STRIPS  
 WITH NOTCHES ON SOUTH & E  
 NOTCHES ON EAST END 66 ft.

13" FIR NGL/E 167 L  
30 CEDAR SGE 48 L  
11" FIR SSI 3/4 W 140 L  
16" FIR NGS 1/4 W 155 L

SECTION CORNER  $\frac{21.25}{21.25}$  THURSE

FOUND STONE MARKED AS  
DESCRIBED  
22" T FIR STUE 30' HIGH OVERGROWN  
FACE N/ALE 84

66" CEDAR D.V. SCRIPE 56.3E 45'  
48" T. FIR OVERGROWN S 2W 92'  
Decayed fir stub 1' high N65W 102'

13. Fir

ABT FILE

10/25/2017

~~21326  
547~~

5-19-55 5:19 PM

17-18

CHRISTIANITY AT TOP DRILL COVER  
STONE

102272

BOOK 6/5 PAGE 7

State of Washington  
DEPARTMENT OF NATURAL RESOURCES  
BUREAU OF SURVEYS AND MAPS  
LAND CORNER RECORD

21	22
28	27

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. R-13

Segregated Surveys:

Name: n/a

Corner Number: n/a

## 1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 bearing trees.

No subsequent restoration found.

FILED FOR RECORD  
SKAMANIA CO. WASH.  
BY JAM 1018D

## 2. Description of Evidence Found:

GLO stone with proper notches.  
32" T. fir stub at N21E 84 feet with overgrown face.  
66" cedar S63E 45 feet with visible scribe.  
48" T. fir at S52W 92 feet with overgrowth.  
Decayed fir stub, 1 foot high, at N65W 102 feet.

DEC 1, 1986 PM '86

d. New Ap.

AUDITOR

GARY M. OLSON

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 49. Date of work June 30, 1986.

Corner is the original andesite stone.

See reverse side for corner diagram.

## SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 19, 1986.

Signature

*H. Thomas Laird Jr.*

21490

Certificate No.



## AUDITOR'S CERTIFICATE

Filed for record this \_\_\_\_\_ day of \_\_\_\_\_ 19 \_\_\_\_\_ at \_\_\_\_\_ M.  
In Book \_\_\_\_\_ of \_\_\_\_\_ at page \_\_\_\_\_ at the request  
of Washington State Department of Natural Resources.

Registered

Index, Dir

County Auditor