
27 | 26 34 | 35

BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

			÷
T 6 N, R 5 E, W.M.	Skamania Count		
Segregated Surveys: Name: n/a		Corner Code No	منزان ها استانت
		Corner Number:	n/a
1. History of Corner Establishmer	nt and Subsequent 1	Restoration:	
Originally established in 1909 by dead bearing trees.	GLO surveyor C. F	rank Rhodes with a n	otched stone and
No subsequent restoration found.			
		_	
		/	W //
		FILED FOR RECORD SKAHANIA CO. WASI BY	
2. Description of Evidence Found:		_UEG21, PM '80)
GLO stone with proper notches. 38" fir stub at N60E 67 feet. 50" fir snag at S67E 5 feet (GLO b 40" fir snag at S38W 49 feet with 34" fir snag at N22W 36 feet.	earing was S50°E). visible scribe.	AUDITOR GARYM. OLSON	
	<i>—</i> — .	· •	- N
	7 7		10
		\sim)]
3. Describe Monument, Accessories Diagram corner and indicate mer Book No. 601.07, Page No. 51.	Clalan and reteren	ce to man of record	Corner Location. Surveyor's Fiel
Replaced original stone with DNR at	luminum monument w	ith stamped cap.	
See reverse side for corner diagram			
	· -		
SURVEYOR'S CERTIFI	CATE	[Seal]
This corner record correctly representations of the provisions of Chapter 50, Date: November 19, 1986.	lon in compliance	THOMAS L	B F
Staneture Homes Loudh	21490	M JEE	9
Signature	Certificate 1	No.	
		NO. CANO	
A	AUDITOR'S CERTIFICA	ATE	
Filed for record this day	of	19at	м.
In Book of Washington State Department of N	atural Resources.	at page	at the request
	Registered .C	County	Auditor
the contract of the contract o		- Journey	



6051

T,

Ġ

50"dea/fir 550E 35" dead lir

Ne Constant TO BELLEVIE

24" docto NOW 546

Section Corner 34 135 TON RUE

Found TX11 X 12 sandstone w/ all 640 notches Forno':

38" fir stib Neos 34" france NZZW to the snap 538W

State of Washington DEPARTMENT OF NATURAL RESOURCES

BUREAU OF SURVEYS AND MAPS

LAND CORNER RECORD

Skamania County Corner Code No. V-17 T 6 N, R 5 E, W.M. Segregated Surveys: Corner Number: n/a Name: n/a 1. History of Corner Establishment and Subsequent Restoration: Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 dead bearing trees. No subsequent restoration found. FILED FOR RECORD SKAMARIA DO. WASH BY TON LINER 2. Description of Evidence Found: (4) (1) GLO stone with proper notches. GARY M. OLSON 38" fir stub at N60E 67 feet. 50" fir snag at S67E 5 feet (GLO bearing was S50°E). 40" fir snag at S38W 49 feet with visible scribe. 34" fir snag at N22W 36 feet. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 51. Date of work June 30, 1986. Replaced original stone with DNR aluminum monument with stamped cap. See reverse side for corner diagram. [Seal] SURVEYOR'S CERTIFICATE This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 19, 1986. Thomas Loud f AUDITOR'S CERTIFICATE 19___ _day of __ Filed for record this ____

of

of Washington State Department of Natural Resources.

at page __

County Auditor