102279

State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. Z-5

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO Surveyor C. Frank Rhodes, with a stone and 4 BTs.

No subsequent restoration found.

FILED FOR RECORD SKAHARA CO. WASH

2. Description of Evidence Found:

25 PM '86

GLO stone with proper notches. 40" fir BT snag at S17W 62.5 feet. 42" fir BT snat at N28W 36.4 feet. Rotted hemlock BT stump at S53E 33.6 feet. Rotted hemlock BT stump at N53E 34.0 feet.

AUDITOR GARY H. OLSON

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 47. Date of work June 18, 1986.

Corner is the original granite stone.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 24, 1986.

H. Shower Land

21490 Certificate No. [Seal]



AUDITOR'S CERTIFICATE

	-6	19	at	M
Filed for record this	day of	at page _	a	t the reques
In Book of Washington State Departmen	nt of Natural Reso	urces.	*	
	وستها فه در این به د در در در این در در این در		County Aud	tor

corrir is the granite stone 30000 mg originally set in 1909. SE 87 9 34.30 **2 *** *** Fours granes cone, exposma 11, with 1301 G. S. S. C. S. C. Refled Kember Comes & Cost E, 33.6" NS36 34.0' 2000 Acon 1972 1000 BOOK no serialing visit on any 37 36.4' 517W 62.51 Potted here bed reven no o 100 4 24 22 GH 6 12 12 15 15. (10/V) \$ 605 Jy . 711 10, 41 200 toma!

Court State of the Court of the

State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS

 $\frac{31}{6} \frac{32}{5}$

LAND CORNER RECORD

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. Z-5

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO Surveyor C. Frank Rhodes, with a stone and 4 BTs.

No subsequent restoration found.

FILED FOR RECORD SKAHAN A SO. WASH BY TOM LATED

2. Description of Evidence Found:

GLO stone with proper notches.
40" fir BT snag at S17W 62.5 feet.
42" fir BT snat at N28W 36.4 feet.
Rotted hemlock BT stump at S53E 33.6 feet.
Rotted hemlock BT stump at N53E 34.0 feet.

ALIDITOR GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 47. Date of work June 18, 1986.

Corner is the original granite stone.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 24, 1986.

Signature Zaudh

21490 Certificate No.

AUDITOR'S CERTIFICATE

THOMAS LAIRD IN

	manard th		day o	o f	19	at	M.
Filed for the Book		•	of of		at page	at at	the request
of Washing	ton State	Departmen	nt of Na	Resistand		· .	
				5	C	County Audit	or