

102281

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

32	33
5	4

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. Z-9

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 dead BTs.

No subsequent restoration found.

FILED FOR RECORD
SKAMANIA CO. WASH
BY

DEC 1 1 27 PM '86

2. Description of Evidence Found:

Original stone with proper notches.

50" fir stub BT, 12 feet high, at S14E 51 feet.

40" fir stump BT, crushed by 2 windfalls, at S37W 7 feet.

40" fir stump BT at S4W 20 feet.

Rotted remains of 24" fir at N79E 25 feet.

AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field
Book No. 601.07, Page No. 54. Date of work June 12, 1986.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: November 18, 1986.

H. Thomas Laird Jr.
Signature

21490
Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered

County Auditor

188801

54

Laird
Bressler
Harris

6-12-86

(Rhodes)

GLE Survey of 1909
Set Sandstone 15x11x9 with 4 notches
on east and 2 notches on west.



24" dead fir	N77E	38L	25.1
50" dead fir	S14E	77L	50.8
40" dead fir	S37W	10L	4.6
45" dead fir	N4W	31L	20.5

Section Corner $\frac{22.33}{514}$ T S 66 N R 5 E

Found 13x10x7 Sandstone with all GLO notches.
Rotted remains of 24" fir @ N79E, 25'
50" fir stub, 12' high, @ S14E 51'
40" fir stump crushed, 2 loss, @ S37W 7'
45" cut fir stump @ N4W 20'

The above measurements are to the centers.
No axe work or scribing visible.

Placed Alum log on Huffman Peak trail, which
is approx 330' east of corner



Corner is an Alum Mon with 50x3" above
ground. It is set in the bulldozed out
portion of a 42" log. (The 50x37 bike
off and fall on corner) Set original stone
on south side of monument

102281

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

32	33
5	4

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. Z-9

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 dead BTs.

No subsequent restoration found.

FILED FOR RECORD
SKAMANIA CO. WASH
BY TOM LAIRD

DEC 1 27 PM '86

2. Description of Evidence Found:

Original stone with proper notches.

50" fir stub BT, 12 feet high, at S14E 51 feet.

40" fir stump BT, crushed by 2 windfalls, at S37W 7 feet.

40" fir stump BT at S4W 20 feet.

Rotted remains of 24" fir at N79E 25 feet.

AUDITOR
GARY M. OLSON

- 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.**
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 54. Date of work June 12, 1986.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: November 18, 1986.

H. Thomas Laird Jr.
Signature

21490
Certificate No.

**AUDITOR'S CERTIFICATE**

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered

County Auditor