## 102283

# State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

33 34

Skamania County

T 6 N, R 5 E , W.M.

Corner Code No. Z-13

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 dead BTs.

Recovered in 1966 by James E. Jelley, BLM. He set BLM pipe and cap and scribed 4 new BTs.

FILED FOR RECORD SKAMANU. CO. WASH BY

DEC | | 29 PM '86

2. Description of Evidence Found:

Original stone with proper notches.
BLM pipe and stamped brass cap.
30" fir stub BT at N22W 19.8, with visible scribing.

AUDITOR GARY H. OLSON

30" fir stub BT at N22W 19.0, With 47024 4 - 1966 BTs.

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
 Diagram corner and indicate meridian and reference to map of record. Surveyor's Field
 Book No. 601.07, Page No. 50. Date of work June 26, 1986.

Corner is BLM pipe and stamped brass cap.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 18, 1986.

Helmon Landh

21490


Certificate No.

AUDITOR'S CERTIFICATE

THOMAS LAIRD IN

[Seal]

	record this	f	19at page	atat th	M. ne request
OI ASSUL		Registered Inalized, Life Co	Co	ounty Auditor	



#### State of Washington DEPARTMENT OF NATURAL RESOURCES

## **BUREAU OF SURVEYS AND MAPS** LAND CORNER RECORD

Skamania County

T 6 N, R 5 E , W.M.

Segregated Surveys:

Name: n/a

Corner Code No. 2-13

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 dead BTs.

Recovered in 1966 by James E. Jelley, BLM. He set BLM pipe and cap and scribed 4 new BTs.

FILED FOR RECORD SKAMARIA QO, WASH BY TON LAND

2. Description of Evidence Found:

Original stone with proper notches. BLM pipe and stamped brass cap. 30" fir stub BT at N22W 19.8, with visible scribing. 4 - 1966 BTs.

Cl. Jus Dep. AUDITOR GARY H. OLSON

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 50. Date of work June 26, 1986.

Corner is BLM pipe and stamped brass cap.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in co with the provisions of Chapter 50, Laws of 1973. Date: November 18, 1986.

Certificate No.

[Seal]

### AUDITOR'S CERTIFICATE

Filed for record this				da	y of		19_	at _	M	
In	Book			of			at page		at the	request
of	Washington	State	Department	of	Natural	Resources.				
٠.٠				•			•			
		:			-	pistered S		County	Auditor	
		•	•							

FILED FOR RECORD

SKAMANIA CO. WASH

BY MYRTH GERREPREN

NO 3 11-12 NA 06

AUDITOR

GARY M. OLSON