


103458

BOOK 4/9 PAGE 72



T. N. TRANTOW SURVEYING

412 W. Jefferson P.O. Box 287

Bingen, Washington 98605 (509) 493-3111

LAND CORNER RECORD

T. 4 N, R. 9E, W.M. SKAMANIA County Corner Code No. R-17

Name: Corner to Sections 22, 23, 26 & 27 Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration: 2. Description of Evidence Found:

GLO established this corner in 1892

Circa 1946, Broughton Lumber Co. set 1 1/2" iron pipe from two BT's

DNR in 1977 survey of Section 23 replaced IP with standard DNR concrete monument

2. No change made to description of corner. Corner is in good condition, and is described from previous record. Clearcut area is very brushy.

FILED FOR RECORD
SKAMANIA CO. WASH
BY TERRY N. TRANTOW
JUN 7 12 56 PM '87
AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record.

F.B. No. 40922 Page No. 4 Job No. 87325 Date of Work 11 April 1987

From the DNR monument bear:

24" D-fir stump, S58W, 6.87 ft

60" D-fir stump, S79E, 15.42 ft. BT

48" D-fir stump, N42E, 49.30 ft. BT

44" D-fir stump, N04E, 14.59 ft.

Marked with DNR witness tags

T4NR9E
522/523
527/526
1977

Washington Plane Coordinates: South Zone, Y 176563.28, X 1707166.54
third Order Accuracy. Derived From: DNR #2 3N-9E & DNR #3 4N-10E

Pin Pointed on Photo No. NA Symbol Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.

Signature

Terry N. Trantow

Date 30 May 1987

Certificate No. 15673



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at
Book of at page at the request of

T. N. TRANTOW SURVEYING

County Auditor

Registered C
Indexed, sir
Indirect
Filed
Filed