

LAND CORNER RECORD

T. 4 N. R. 9E, W.M.
Segregated Surveys:
Name: _____
County: SKAMANIA
Corner Code No. C-16
Corner No.: _____
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

NONE

FILED FOR RECORD
SKAMANIA CO. WASH
BY TERRA SURVEYING

Oct 27 3 51 PM '87

2. Description of Evidence Found:


NONE

A. New, Dep.
AUDITOR
CARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 10 Page No. 34 Date of work: 7-87

SET STANDARD 2 1/2" x 30" FOREST SERVICE ALUMINUM PIPE / CAP 2 1/2" IN THE GROUND FROM WHICH BEARS:

5/8" x 30" IRON ROD, N 58° 26' 40" E, 12.16 FT.
5/8" x 30" IRON ROD, S 31° 16' 20" W, 7.80 FT.
IRON RODS HAVE PLASTIC "TERRA-PLS 18731" CAPS. NO SUITABLE TREES AVAILABLE, CORNER IS IN CLEAR CUT. SET CARSONITE GUARD POST NEAR MONUMENT.



Washington Plane Coordinates: _____ Zone, Y _____, X _____
Order Accuracy. Derived From: _____
Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8/18/87

Signature Roy O. Gaylord Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M. In Book _____ of _____ at page _____ at the request of _____

County Auditor

Registered S
Indexed ir
In _____
M. _____

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.