

LAND CORNER RECORD

SKAMANIA

County

Corner Code No. R 23

T 5 N, R 9E, W.M.

Segregated Surveys:

Name:

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ESTABLISHED BY DEPUTY SURVEYOR JACOB RICHARDSON UNDER HIS CONTRACT NO. 383, OCTOBER/NOVEMBER 1892. SET POST FROM WHICH BEARS:

16" FIR, N 47° 30' W, 41KS, MARKED "SC 1/4 SBT"

18" FIR, S 22° E, 391KS, "SC 1/4 SBT"

FILED FOR RECORD
SKAMANIA CO WASH
BY TERRA SURVEYING

2. Description of Evidence Found:

NO REMAINS OF GLO EVIDENCE FOUND.

OCT 28 9 52 AM '87

AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

10 Page No. 9 Date of work 7-87


SET STANDARD FOREST SERVICE 2 1/2" X 30" ALUMINUM PIPE/CAP 24" IN THE GROUND, FROM WHICH BEARS:

5/8" X 30" IRON ROD N 64° 45' E, 13.1 FT.

5/8" X 30" IRON ROD S 44° 30' W, 20.1 FT.

IRON RODS HAVE PLASTIC "TERRA-PLS 18731" CAPS.

SET CARBONITE GUARD POST NEAR MONUMENT. CORNER FALLS IN NEW CLEARCUT, NO SUITABLE TREES AVAILABLE.



Washington Plane Coordinates: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 9/87 18731

Signature

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In Book of at page at the request of

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section Chapter 50, Laws of 1973.

Registered S

Indexed, Jir

Indirect

Filed

M.I.L.d