

LAND CORNER RECORD

T. 4 N, R. 7E, W.M. Skamania County
Segregated Surveys: Corner Code No. Z-7
Name: one-quarter Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally set by Deputy Robert F. Whitham in 1903 under Contract No. 600.
Set Hemlock post
14" Hemlock N62 $\frac{1}{2}$ W-65 lks.

2. Description of Evidence Found:

Searched for not found-the corner was probably destroyed by wildfire about 50 years ago.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 2 Page No. 5 Date of work 6/87

Set 2 $\frac{1}{2}$ "x30" Alum. pipe with a 2 $\frac{1}{2}$ " Alum. cap 27" in ground stamped:

New Bearing Trees:

8" D-Fir N63 $\frac{1}{2}$ W-18.2' scribed X S32BT

13" D-Fir N8 $\frac{1}{2}$ E-20.5' scribed X S32BT

R/R spike in base of 12" D-Fir S47W-3.95' to spike.

Both BT's have a 1" Brass disk stamped LS 16337.

Set guard posts East & West with decals 54-2 & survey marker.

Nailed 54-9 & BT signs to BT's & painted band & blazes red.

T4N R7E
S32
X
T3N
1987
LS 16337

Washington Plane Coordinates: Zone, Y

Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 9/22/97

Signature *Larry D. Bishop*

16327
Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this 19 day of at M. In Book of at page at the request of

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

Registered S
Indexed, Dir
Indirect
Filed
Mailed

