
State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

1/4 18

Skamania County Corner Code No. N-3 T 2 N, R 5 E, W.M. Segregated Surveys: Corner Number: n/a Name: n/a 1. History of Corner Establishment and Subsequent Restoration: Originally established by GLO in 1859 with a post and two bearing trees. Subsequently restored by Clark La Barre in 1913 from "original witness tree." Mr. La Barre scribed two additional witness trees. In 1979, Olson Engineering set a 3/4" iron pie with brass cap from Mr. La Barre's witness trees, which then were stumps. 2. Description of Evidence Found: Above-described pipe with unstamped cap. FILED FOR RECORD Three Olson Engineering reference trees. skamania co. Wash TY Dale Fan 22, 2 04 PM '88 d. Trub, Dep. AUDITOR 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.29, Page No. 4. Date of work January 22, 1988. See reverse side for corner diagram. Pin Pointed on Photo No. _____, Date _____, Located at [Seal] SURVEYOR'S CERTIFICATE This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: February 17, 1988. AUDITOR'S CERTIFICATE Filed for record this _____ day of _ at the request of Washington State Department of Natural Resources.

County Auditor Registered S Indexed, Dir Silverd



BOOK 2/5 PAGE 37