

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

1/4 $\frac{7}{18}$

Skamania County

T 2 N, R 5 E, W.M.

Corner Code No. J-3

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established by GLO in 1859 with a post and two bearing trees. Subsequently restored with a 7/8" iron pipe by persons unknown.

2. Description of Evidence Found:

7/8" iron pipe.

FILED FOR RECORD
SKAMANIA CO. WASH
BY D.N.R.

FEB 22 2 10 PM '88
A. N. W. S. Dep.
AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.29, Page No. 3. Date of work January 20 and 27, 1988.

Corner is a 7/8" iron pipe with a yellow plastic survey cap.

See reverse side for corner diagram.

Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: February 17, 1988.

H. Thomas Laird Jr. 21490
Signature Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19 _____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

County Auditor _____ Registered _____
Indexed, Dir _____
Indirect _____

GLO Survey of 1859

42.00	Set post		
	10" dogwood	S38E 68L	44.08
	12" dogwood	North 25L	16.5

1/4 corner $\frac{7}{18}$ T2N R5E

Found no GLO evidence

Ed. 7/8" O.D. Pipe. A steel post with reflector. A Div. of forestry tag (F. McKay & F. Laws) No date AND a plain tag - Roy Kenny 5-21-66 - LARRY
Kenny 12-4-68

Other surveys:


Germanson - Book 2, pg 114 Skamania Co.

Germanson's ROS shows a 1 1/2" pipe at this corner. His field notes show it as a 1" pipe.

1-27-88
1-20-88

GORDON-BRESSLER
Laid

600.2



The corner is a 7/8" O.D. Galv. Pipe upon which I placed a plastic survey cap marked "Laid 21490, DNR" Above ground. The corner lies on hillside sloping to SW.

A CARSONITE post is set 2.3' East of corner