

105006

RES 20-1808(9-77)

BOOK 5/4 PAGE 10

LAND CORNER RECORD

T. S N, R. 9E, W.M.
Segregated Surveys:SKAMANIA

County

Corner Code No. 2-19

Name:

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ESTABLISHED by DEPUTY Surveyor JACOB RICHARDSON UNDER CONTRACT NO 383, OCTOBER, 1892. SET POST FROM WHICH BEARS:

6" FIR, SSW, 23 LKS. SCRIBED "SC 1/4 SBT"

14" FIR, N 18-30E, 71 LKS, SCRIBED "SC 1/4 SBT"

2. Description of Evidence Found:

1/2" IRON SPIKE, UNKNOWN ORIGIN, FROM WHICH:

6" Doug FIR, Now 26" Doug fir, BEARS SSW, 15.1', HEALED BLAZE

14" " " , Now 41" " " , " N 18-30E, 46.86', HEALED BLAZE


3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 4 Page No. 6 Date of work 3-23-87

SET STD 2 1/2" x 30" ALUMINUM PIPE AND CAP, 24" IN THE GROUND FROM WHICH

17" Doug fir BEARS S12W, 14.15', SCRIBED "S2BT"

22" Doug fir. BEARS N 79-30E, 5.35', SCRIBED "1/4 S35 SC BT"

Trees are painted, signed and have BRASS WASHERS "PLS 18731." SET GUARD POST WITH proper CONTRACT SIGNS. PLACED SPIKE IN HOLE WITH MONUMENT

Washington Plane Coordinates: _____ Zone, Y _____, X _____
Order Accuracy. Derived From: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Dated APR 12 1988

Signature

Certificate No. 18731

AUDITOR'S CERTIFICATE

For record this _____ day of _____ 19____ at _____ M. In _____ of _____ at page _____ at the request of _____

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

FILED FOR RECORD
SKAMANIA
BY TERRA
SURVEYING
APR 14 12 01 PM '88AUDITOR
GARY M. OLSON