

107747

BOOK 6/6 PAGE 55

LAND CORNER RECORD

HAMPSTUR CORPORATION
1010 Douglas A3
LONGVIEW, WASHINGTON 98632

T. 6 N. R. 6 E. W.M.

SKAMANIA

County

Segregated Surveys:

Corner Code No. G-5

Name: 1/4 S. 7/ S. 8

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

In 1921, Chester Pecore set a 1"x36" iron pipe with a brass cap for the corner while working under GLO contract, group #19. The corner has been used by various surveyors since that time. On July 28, 1988, R. Bogdon (from HAMPSTUR CORP.), found remains of both original BT's and the original monument lying on the ground. He reset the original monument back in its original position determined from the found BT's, added 2 RP's and set a steel reference post, as shown in the diagram below, while working on a "corner restoration" project for PLUM CREEK TIMBER COMPANY, under the direction of C. Hampton, LS #18,087.

2. Description of Evidence Found:

ORIGINAL GLO MONUMENT (1921): Found the 1"x36" original iron pipe with brass cap, lying on the ground--reset mon. in original position determined from the found BT's.

ORIGINAL BT's:


- 10" Fir, S07°E--23 lks.; found root crown in record position.
- 12" Fir, S74°W--18 lks.; found 26" stump, 3 ft. high, at record position.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

PS-056 Page No. 24 Date of work 7-28-88

LOCATION:

- on the Northern point of a spur ridge.
- approx. 200 ft. South of a creek, which bears to the Northeast.
- on a 75% North slope.
- 225 ft. North of a logging road, which bears N65°W & N82°E; being located South of a "Y" in the same road.
- an abrupt drop-off is 20 ft. North.
- S50°W, approx. 400 ft. from a switchback in road #10.



Washington Plane Coordinates:

Zone, Y

X

Order Accuracy. Derived From:

Pin Pointed on Photo No.

Date

Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 28, 1989

Signature

Calvin J. Hampton, PLS

LS #18,087

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M. In _____ Book _____ of _____ at page _____ at the request of _____

County Auditor

Registered

Indexed, Sir

Indirect

Filed

Mailed

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.