



107756

LAND CORNER RECORD

BOOK 7/6 PAGE 70

HAMPSTUR CORPORATION
1010 Douglas A3
LONGVIEW, WASHINGTON 98632

T 7 N R 6 E. SKAMMIA County
Segregated Surveys: Corner Code No. Z-3
Name: S. 1/4 corner of Section 31 Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally established in 1900, by Lewis Shelton under GLO contract #552. It was then remonumented with a 1"x36" iron pipe and brass cap by Chester Pecore, while working under GLO contract, group #19. The D.N.R. then replaced the original pipe with a concrete mon. in 1987 and buried the pipe next to the new mon., as shown in the diagram below. Then on July 28, 1988, R. Bogdon (from HAMPSTUR CORP.), located the above corner and refreshed the RP's and set a steel reference post, as shown below, while working on a "corner restoration" project for PLUM CREEK TIMBER COMPANY, under the direction of C. Hampton, PLS #18,087.

2. Description of Evidence Found:

1921 ORIGINAL GLO MONUMENT: found buried next to the DNR monument set in 1987.

ORIGINAL (1921) BT's:

-10" Fir, N02°E--11 lks.; fd. a 10" stump, 1 ft. tall with "BT tag"

-10" Fir, S061°E--12 lks.; fd. a 14" stump, 1 ft. tall with "BT tag"

SUBSEQUENT RESTORATION:

Found the "DNR-mon." as shown in the diagram below along with 4 RP's also shown in the diagram below.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. PS-056 Page No. 27-28 Date of work 7-28-88

LOCATION:

- on a flat area, 25 ft. North of a 25% South slope.
- approx. 165 ft. South of an old E-W cutting line.
- in approx. 4 yr. old reprod.
- approx. 580 ft. West of the SW corner of an existing stand of mature Fir.
- 135 ft. North of road #1060, which bears S86°W-N86°E; at a point which is 590 ft. Westerly of a culvert under the road at a switch-back.
- 75 ft. East of "PT" on spur road, which bears North-South.

set a 4"x4"x8' treated post with location tag on North edge of road, tag reads "North-119"

Washington Plane Coordinates:

Zone, Y

X

Order Accuracy. Derived From:

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 28, 1989

Signature Calvin J. Hampton, PLS

LS #18,087

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M. In _____
Book _____ of _____ at page _____ at the request of _____

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

Registered
Index
Filed
Mailed
9-1-89