



107759

BOOK 7/6 PAGE 73

## LAND CORNER RECORD

HAMPSTUR CORPORATION  
1010 Douglas A3  
LONGVIEW, WASHINGTON 98632

T 7 N R 6 E. W.M. SKAMANIA County  
Segregated Surveys: Corner Code No. Z, 9-10  
Name: MEANDER CORNER, East of SW. cor. Sec. 33 Corner No.:  
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

## 1. History of Corner Establishment and Subsequent Restoration:

This corner was established by N.W. Pettijohn in 1957, while performing a survey for PACIFIC POWER AND LIGHT CO., when surveying the limits of Swift Reservoir. The concrete monument shown in the diagram below was set at that time. The corner has been used by various surveyors since that time for various projects. On August 16, 1988, R. Bogdon (from HAMPSTUR CORP.), found and referenced the corner while working on a "corner restoration" project for PLUM CREEK TIMBER COMPANY, under the direction of C. Hampton, PLS #18,087. Refer to the diagram below for references made at that time.

## 2. Description of Evidence Found:

Found the 3" brass cap in 8" dia. concrete monument, set flush to the ground, as set in 1957, as noted above and shown below.

Found no RP's.

## 3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. PS-056 Page No. 42 Date of work 8-16-88

## LOCATION:

- approx. 100 ft. East of Swift Res.
- on an existing USFS posted East-West line.
- on an existing timber type line, with a mature stand of Fir to the South and a younger stand of mixed timber to the North.
- 10 ft. North of an old cat road, which bears East and West.

NEW RP  
5" FIR, SCRIBED  
[MC 18133 RP]  
R-R SPIKE IN CTR.  
"LOC-TAG"

SET 5/8" STEEL  
FENCE POST WITH  
"LOC-TAG"

DECL: 19° E.

MC.

533.34

181M

FD. 3" BRASS CAP  
IN AN 8" DIA. CONC.  
MON. AS SET FLUSH  
TO GROUND IN 1957,  
FOR MEANDER CORNER.

NEW RP  
3" FIR, SCRIBED  
[MC 18134 RP]  
R-R SPIKE IN CTR.  
"LOC-TAG"

Washington Plane Coordinates: Zone, Y  
Order Accuracy. Derived From: X

Pin Pointed on Photo No. Date Located at

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 28, 1989

Signature

Calvin J. Hampton, PLS

LS #18,087

Certificate No.



## AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In  
Book of at page at the request of

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

Registered  
Indexed  
Indirect  
Filed  
Noted