

BRASS

Q

X

P

DETAIL NO SCALE 60" STUMP OF-1883 G.L.O. FIR LINE TREE 2.31 NORTHEAST CORNER SECTION 24 FD: 60" FIR SNAG BT WITH OLD TAGS AT S48W 21.12 FEET, 30" HEMLOCK BT UPROOT AT N85W 69.3 ON 3-24-82, THIS SURVEY SET A 3" CYLINDRICAL DNR CONCRETE MONUMENT WITH STAMPED BRASS CAP AT RECORD BEARING AND DISTANCE FROM THE 60" FIR SNAG BT. THE DISTANCE AND BEARING TO THE HEMLOCK BT UPROOT FIT. 3 REFERENCES WERE NOTED. ON 2-20-85, I FILED AN LCR WITH SKAMANIA COUNTY UNDER AUDITOR'S FILE NO. 98937 IN BOOK 3/5 OF MONUMENTS AT PAGE 6. ON 8-27-92, THIS CORNER WAS VISITED AND THE 1982 RP'S WERE FOUND TO BE INTACT. THE TREE DIAMETERS WERE UPDATED. 28" FIR AT N78E 16.77 FEET TO ALUM NAIL FACING CORNER. 11" FIR AT S47E 10.68 FEET TO ALUM NAIL FACING CORNER. 13" FIR AT S74W 39.66 FEET TO ALUM NAIL FACING CORNER. NORTHWEST CORNER SECTION 19 FD: 60" FIR STUB AT N67W 16.5 FEET -- THIS WAS A 1883 BT, THE 1892 RESURVEY DESTROYED THE MARKS ON THIS BT. 16" FIR BT STUB WITH AXE MARKS AT N45E 19.1 ON 3-24-82, THIS SURVEY SET A 3" CYLINDRICAL DNR CONCRETE MONUMENT WITH STAMPED BRASS CAP AT THE DISTANCE-DISTANCE INTERSECTION FROM THE FACES OF THE TWO FOUND BT'S. 3 RP'S WERE NOTED. ON 2-20-85, I FILED AN LCR WITH SKAMANIA COUNTY UNDER AUDITOR'S FILE NO. 98936 IN BOOK 3/6 OF MONUMENTS AT PAGE 38. ON 8-27-92, THIS CORNER WAS VISITED AND THE 1982 RP'S WERE FOUND TO BE INTACT. THE TREE DIAMETERS WERE UPDATED. 10" FIR AT S72E 31.66 FEET TO ALUM NAIL 9" FIR AT S3W 10.19 FEET TO ALUM NAIL FACING 18" FIR AT S72W 29.17 FEET TO ALUM NAIL FACING CORNER. NORTHEAST CORNER SECTION 25 CALCULATED CORNER ON 10-13-83, THIS SURVEY SET A 3" CYLINDRICAL CONCRETE MONUMENT WITH STAMPED BRASS CAP AT THE SINGLE PROPORTION POSITION OF THE NORTHEAST CORNER OF SECTION 25. 4 RP'S WERE NOTED. ON 2-20-85, I FILED AN LCR WITH SKAMANIA COUNTY UNDER AUDITOR'S FILE NO. 98938 IN BOOK 3/5, 3/6 OF MONUMENTS AT PAGE 8. ON 7-27-92, THIS CORNER WAS VISITED AND THE 1983 RP'S WERE FOUND TO BE INTACT. THE TREE DIAMETERS WERE UPDATED. 55" FIR STUMP AT N74E 15.17 FEET TO ALUM NAIL IN SOUTH SIDE. 30" FIR STUMP AT SJE 12.66 FEET TO ALUM NAIL 12" ALDER AT S80W 12.82 FEET TO ALUM NAIL IN 20" HEMLOCK STUMP AT N55W 55.14 FEET TO ALUM NAIL IN SW SIDE. FB 600.21A PAGE 34

 $\langle D \rangle$ EAST 1/4 CORNER SECTION 25 CALCULATED CORNER ON 10-17-83, THIS SURVEY SET A 3" CYLINDRICAL DNR CONCRETE MONUMENT WITH STAMPED BRASS CAP AT THE SINGLE PROPORTIONED POSITION OF THE EAST 1/4 CORNER OF SECTION 25. 4 RP'S WERE NOTED. ÓN 2-28-85, I FILED AN LCR WITH SKAMANIA COUNTY UNDER AUDITOR'S FILE NO. 98972 IN BOOK 3/5 OF MONUMENTS AT PAGES 12 AND 13. ON 8-27-92, THIS CORNER WAS VISITED AND THE 1983 RP'S WERE FOUND TO BE INTACT. THE TREE DIAMETERS WERE UPDATED. 26" FIR AT S52E 23.92 FEET TO ALUM NAIL IN SW SIDE. 23" FIR AT S39W 44.18 FEET TO ALUM NAIL IN SE SIDE. 17" FIR AT N72W 17.98 FEET TO ALUM NAIL IN SOUTH SIDE. 21" FIR AT N13W 37.49 FEET TO ALUM NAIL IN WEST SIDE. FB 600.21A PAGE 36 $\langle E \rangle$ SOUTHEAST SECTION 36 (TOWNSHIP CORNER) ACCEPTED CORNER

CORNER.

NORTH SIDE.

FD: SKAMANIA COUNTY ENGINEER'S DEPARTMENT 1" IRON PIPE WITH STAMPED BRASS CAP, DATE SET IS UNKNOWN; 57" FIR BT STUMP AT S83E, 4.25 FEET TO FACE (NO SCRIBING). ON 9-17-81, THIS SURVEY FOUND THE PIPE TO BE THIS CORNER WAS USED ON ROS FILED IN BOOK 2 OF SURVEYS AT PAGE 271, RECORDS OF SKAMANIA COUNTY, AND ON DNR FINAL MAP NO. 801 FILED IN BOOK 3 OF SURVEYS AT PAGES 68-72. ON 9-25-91. THE PIPE WAS FOUND TO BE FIRMLY SET AND THE FOLLOWING REFERENCES WERE NOTED:

DNR CARSONITE WITNESS POST AT NORTH, 3 FEET. 57" FIR STUMP (BT) AT SB3E 5.38 TO ALUM NAIL IN CORE WOOD ON TOP. 25" FIR AT S38W 31.70 FEET TO ALUM NAIL IN SE SIDE. 14" ALDER AT N10W 40.46 FEET TO ALUM NAIL IN EAST SIDE. FB 600.33B PAGE 47

S Ω 田 9 S RANGE 田 RANG SEARCHED FOR NOT FOUND. SEARCHED FOR NOT FOUND. TWP.3 NORTH TWP.2 NORTH "PROSPECTOR CREEK"

SURVEY

BOOK

W

,60" STUMP OF 1883

G.L.O. FIR LINE TREE

19 SEARCHED FOR

NOT FOUND.

359107'06"

341.74