

RES 20-1808(9-77)

LAND CORNER RECORD

518	CC
519	

T 10 N, R 6 E, W.M.
 Segregated Surveys:
 Name: _____
 County SKAMANIA
 Corner Code No. N-1
 Corner No.: _____
 Name: _____
 DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

ESTABLISHED BY C.W. PECORE + F.G. BETTS UNDER SPECIAL INSTRUCTIONS
 DATED MARCH 20, 1914, GROUP 17.

2. Description of Evidence Found:


OBT, 14" FIR SNAG 8' TALL, SCRIBES '18CC BT" VISIBLE, BEARS N16½°E, 22.4 FT.
 (34 LNS.) AS PER REC.
 OBT, 18" CEDAR BLOWDOWN, HEALED FACE, BEARS S66°E, 35.0 FT. (53 LNS.) AS PER REC.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. NVM.C-2 Page No. 15 Date of work 9-10-84

At REC. BEAR. + DIST. FROM OBT'S I SET A 2" x 30" AL. PIPE
 WITH 2½" AL. CAP MKD. AS SHOWN →
 26" IN GROUND, IN A MOUND OF STONE.
 NO LIVE TREES IN THE AREA. I SET 2 REFERENCE MONUMENTS
 AS FOLLOWS:

5" x 30" STEEL REBAR WITH 1½" AL. CAP MKD. "TION R6E S18CC RM"
 BEARS N38½°E, 12.85 FT.
 5" x 30" STEEL REBAR WITH 1½" AL. CAP MKD. "TION R6E S19CC RM"
 BEARS S14½°E, 6.57 FT.

TION	TION
RSE	518 CC
S24	519
	R6E
	1984
RLS	16966




Washington Plane Coordinates: _____ Zone, Y
 Order Accuracy. Derived From: _____


Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 9-30-84
 Signature Victor M. Mc Lind Certificate No. 16966



Registered	S
Indexed	S
Indirect	
Filmed	
Mailed	



AUDITOR'S CERTIFICATE

Filed for record this 21 ST day of FEBRUARY 1986 at 10:10 A.M. In
 Book 1216 of MONUMENTS at page 11 at the request of
VICTOR M. MC LIND
Mc Lind by J. D. Davis, Dep.
 County Auditor