

RES 20-1808(9-77)

LAND CORNER RECORD

4520

T. 10 N, R. 6 E, W.M.
Segregated Surveys:

SKAMANIA

County

Corner Code No. P-5

Name:

Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

ESTABLISHED BY C.W. PECORE AND F.G. BETTS UNDER SPECIAL INSTRUCTIONS
DATED MARCH 20, 1914, GROUP 17.

2. Description of Evidence Found:

GRANITE STONE 28" x 11" x 6", MKD. 4520 ON E. FACE, FIRMLY IN GROUND.
28" CEDAR BLOWDOWN, OPEN, ROTTEL FACE WITH FAINT SCRIBES "45", BEARS
S 42 3/4° E, 47.5 FT. (72 LKS.)
20" HEMLOCK BLOWDOWN, HEALED FACE, BEARS N 68° E, 40.3 FT. (61 LKS.)3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.
NUM C2 Page No. 13 Date of work 9-9-84IN PLACE OF FOUND STONE MON. AND AT RECORD. BEAR. + DIST. FROM
OBT'S I SET A 2" x 30" AL. PIPE WITH 2 1/2" AL. CAP MKD. AS SHOWN →
24" IN GROUND, AND BURIED STONE MON. ALONGSIDE.

NO LINE TREES IN AREA. I SET 2 REF. MONS. AS FOLLOWS:



5/8" x 30" STEEL REBAR WITH 1 1/2" AL. CAP MKD. "4520 RM" BEARS
N 34 3/4° E, 23.09 FT.5/8" x 30" STEEL REBAR WITH 1 1/2" AL. CAP MKD. "4520 RM" BEARS
S 21° E, 14.50 FT.

NOTE: THIS CORNER REFERS TO SEC. 20 ONLY.

Washington Plane Coordinates: Zone, Y

Order Accuracy, Derived From:

Pin Pointed on Photo No. Date Located at



Registered	S
Indexed, vir	S
Indirect	
Fitted	
Mailed	


SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter

50, Laws of 1973, Date 9-30-84

Signature Victor M. McLind

Certificate No. 16966



AUDITOR'S CERTIFICATE

Filed for record this 21st day of FEBRUARY 1986 at 10:30 A.M. In
Book 10/6 of MONUMENTS at page 15 at the request of
VICTOR M. McLindJ. M. Olson by J. M. Olson, Dep.
County Auditor