

102264

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

31	32
6	5

Skamania County

T 5 N, R 5, W.M.

Corner Code No. A-5

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes, with a stone and 4 BTs.
No subsequent restoration found.

2. Description of Evidence Found:

GLO stone with proper notches.
40" fir BT snag at S17W 62.5 feet.
42" fir BT snag at N28W 36.4 feet.
Rotted hemlock BT stump at S53E 33.6 feet.
Rotted hemlock BT stump at N53E 34.0 feet.

FILED FOR RECORD
SKAMANIA CO. WASH
BY T. J. L. L. L.
Dec 1 12 17 PM '86
GARY M. OLSON
AUDITOR

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 47. Date of work June 18, 1986.

Corner is the original granite stone.
See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: November 18, 1986.

H. Thomas Laird Jr. 21490
Signature Certificate No.

AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

County Auditor

1. 3000 ft. base N53E 50L 33°
 2. 3000 ft. base N52E 52L 34.0°
 30 3000 ft. base S17W 96L 62.5°
 40 3000 ft. base N28W 55L 36.4°

Section corner $\frac{21132}{618}$ T S 46N R SE

Found granite stone, exposed 4", with
all 618 153000

Found:


40" fir snag @ S17W 62.5'

42" fir snag @ N28W 36.4'

Rotted hemlock stump @ S53E, 33.6'

Rotted hemlock remains @ N53E 34.0'

no scribbing visible on any BT



The corner is the granite stone as
originally set in 1909.