

102265

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

1/4
32
5

Skamania County

T 5 N, R 5 E, W.M.

Corner Code No. A-7

Segregated surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO Surveyor C. Frank Rhodes with a marked stone and 2 dead BTs.

Recovered in 1966 by James E. Jelley, BLM. He set a pipe with BLM cap and scribed 2 new BTs.

FILED FOR RECORD
SKAMANIA CO. WASH
BY J. M. OLSON

2. Description of Evidence Found:

Original stone marked 1/4 (closed four).

BLM pipe with stamped brass cap.

40" cedar windfall BT at S28W 43 feet.

27" fir at 127W 18.91 feet (1966 BT).

20" fir at 137E 15.09 feet (1966 BT).

The last two BT's were felled to allow for a photo target. They are now stumps.

Dec 1 10 PM '86

AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.

Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 45. Date of work June 17, 1986.

Corner is B.M. pipe and cap.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE


[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: November 18, 1986.

Signature

21490

Certificate No.

**AUDITOR'S CERTIFICATE**

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered \$ 1
\$
\$
\$
\$

County Auditor

GLE Survey of 1903

40.00 S- sandstone 20x14x10 marked
1/4 on north face

22" dead hemlock N20E 36L 22.5

40" dead cedar S56W 65L 42.5

Corner recovered by Vanx's Jolley, BLM,
in 1966. He noted the bearing to the
cedar was 30° off. He scribed 2
new BTS:

22" fir N26W 29L 19.1'

22" fir S37E 23.5L 15.5'

1/4 corner 32 T56W RSE

Found original stone 20x14x10 marked
1/4. BLM monument with stamped
brass cap.

Found:

40" cedar windfall @ S28W, 43'

27" fir stump (cut) @ N27W 18.91'

20" fir stump (cut) @ S37E 15.09'

original stone is set on the north
side of the BLM pipe/cap

6-17-86

Hanlin
Bressler 45
001.07

