## State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. R-13

Segregated Surveys:

Corner Number: n/a

Name: n/a

1. history of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 bearing trees.

No subsequent restoration found.

FILED FOR REGURD SKAN HIL CO. WASH

Description of Evidence Found:

GLO stone with proper notches.

32" T. fir stub at N21E 84 feet with overgrown face. 66" cedar S6 E 45 feet with visible scribe.

48" T. fir a: S52W 92 feet with overgrowth. Decayed fir stub, 1 foot high, at N65W 1C2 feet. DEC 1, 1 17 PK 186 a. I kim tot. AUDITOR GARY M. OLSON

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.

Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07, Page No. 49. Date of work June 30, 1986.

Corner is the original andesite stone.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: November 19, 1986.

H. Showar Laurah Signature

AUDITOR'S CERTIFICATE

Filed for record this Comparison State Department of Washington State Department of the comparison of Washington State Department of the comparison o	day of cf of Natural Reso	at page ources.	atat the request
	Register Intervi		County Auditor

1. 30 H. Euros, of 1909 (Encles) TO BE IN SET SON SET SANGET TO COUTE DIDTERS ON SOUTH & E NOTHES ON EAST EDGES. 18' FIR WAIF DE. 30 CEDAR SUBE GEL 11 FR SS134W 1406 16' FIR NOS 461 15-L SECTION CORNER 375 TONPSE FOUND STONE MARKED AS DESCRIBED 32" TFIR STUE 30 HIGH OUTESCOUNT FACE NOZE 89 66" CEDAR UIS SCRIBE 5-38 45 48" TFIR DIRECEMENTH STEEL POL Decayed Fix STUB 1 High 1165W 102 LHISLED AN'T ATOP ORIG COLVE

BRANCE WAR