State of Washington DEPARTMENT OF NATURAL RESOURCES BUREAU OF SURVEYS AND MAPS LAND CORNER RECORD

Skamania County

T 6 N, R 5 E, W.M.

Corner Code No. R-17

Segregated Surveys:

Corner Number: n/a

Name: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established in 1909 by GLO surveyor C. Frank Rhodes with a notched stone and 4 dead bearing trees.

No subsequent restoration found.

FILED TO REGORD <u>. n</u> SFA BY

GARYM, GLECH

2. Description of Evidence Found:

19 7 86 AUDITOR

GLO stone, firmly set, with proper notches. 26" fir stub at N25E 92 feet (hor.) with exe marks.

22" hemlock stub at \$87E 21 feet (slope).

18" hemlock stub at S43W 17.5 feet (slope).

40" fir stub at N35W 8.6 feet (hor.)

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.

Diagram corner and indicate meridian and reference to map of record. Surveyor's Field

Book No. 601.07, Page No. 55. Date of work June 10, 1896. Corner is the original granite stone.

See reverse side for corner diagram.

SURVEYOR'S CERTIFICATE


This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Lews of 1973. Date: November 19, 1986.

11 Shomas Zouth Signature

Certificate No.

21490

[Seal]



AUDITOR'S CERTIFICATE

	AUDITOR IS OFFI		м.
Filed for record this of In Book of Washington State Department o	ay of f Vatural Resources.	at page	t the request
of Washington State 24	Resistered 5	County Aud:	Ltor

LAIRD GORDON G10. of 1909 (CFIANK PH. dec.) 20.00 Se- DIVINX 16 GRAINTE STANG THE 2 NOTCHES ON S. JE. FUGES +301 CHICH: 26' Deno FIR NESE 1401 WK. 9:40 23" Dead HEM CHITE 31 " 2000 16" " Horn 5486 36 " 106 115" FIR N3SW 13 1 255 SECTION CORNER 57/36 7.64, R. 5. E. 13"W FIRA FOUND : SPANITE STONE SET 13" GIFR A FIRMLY IN GROUND WITH 2 NOT CHES ON S. AND E FEGGE THE ROTHED REMAINS OF THE BY S AT CALLED VIST BEARINGS THE CORNER IS GRANITE STONE AS DENLINALY SET BY Rholes in 1909 ...