

102097

State of Washington
 DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

1/4 10/15

Skamania County

Corner Code No. J-15

T 3 N, R 6 E, W.M.

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally set by 1903 GLO survey.
 No restoration found.

2. Description of Evidence Found:

44" hemlock BT at N79W, 76.6 feet.
 Roots of SW BT at S11W, 74 feet.

FILED FOR RECORD
 DEPT. OF NATURAL RESOURCES
 BY *[Signature]*
 Oct 31 11 28 AM '86
E. M. Olson
 AUDITOR
 GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.27, Page No. 52. Date of work 10-28-86.

Set DNR aluminum monument. See sketch on back.

Washington Plane Coordinates: South Zone, Y 156,906.61, X 1,603,388.71 Third Order Accuracy.

Derived from: USC&GS "Mowich" and USC&GS "Lookout Mtn. RM #1".

Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

[Seal]


This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
 Date: October 30, 1986.

Signature

H. Thomas Laird Jr.

21490

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this 31 day of Oct 19 86 at 11:28 A.M.
 In Book 3/6 of Monuments at page 40 at the request
 of Washington State Department of Natural Resources.

Registered E
 Indexed, Dir E
 Indirect _____
 Filmed _____
 Mailed _____

Gary M. Olson by E.M.
 County Auditor