

103618

State of Washington  
DEPARTMENT OF NATURAL RESOURCES  
BUREAU OF SURVEYS AND MAPS  
LAND CORNER RECORD

1/4 1/12

Skamania County

Corner Code No. E-23

T 3 N, R 7 1/2 E, W.M.  
Segregated Surveys:  
Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally set by GLO-No subsequent restoration found.

2. Description of Evidence Found:

Found DNR concrete monument with stamped brass cap set at calculated position.

3 overgrown 1978 R.P.'s.

FILED FOR RECORD  
BY D.N.R.  
AUG 3 2 23 PM '87  
AUDITOR  
GARTH M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.12, Page No. 6. Date of work March 15, 1978, July 14, 1987.

Shown on DNR FM# 315

See reverse side for sketch.


Washington Plane Coordinates. South Zone, Y 161967.88, X 1651650.18 Third Order Accuracy. Derived from: Ties to USC&GS "GREENLEAF" & USC&GS "SEDUM POINT". Pin Pointed on Photo No. \_\_\_\_\_, Date \_\_\_\_\_, Located at \_\_\_\_\_.

SURVEYOR'S CERTIFICATE

[Sea1]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: August 3, 1987.

H. Thomas Laird Jr. Signature 21490 Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this \_\_\_\_\_ day of \_\_\_\_\_ 19\_\_\_\_ at \_\_\_\_\_ M.  
In Book \_\_\_\_\_ of \_\_\_\_\_ at page \_\_\_\_\_ at the request  
of Washington State Department of Natural Resources.

Registered S  
J. Jir

County Auditor

7-14-87\*  
3-15-75

THIRD \* LAIN  
SNOW GORDON 600.15  
GORDON  
INGENIARD HANLIN

SET 3" CYLINDRICAL  
DNR CAMP MARK  
4" ABOVE GROUND  
100 ± SOUTH OF OLD  
CUT ROAD



NORTH 1/4 COR SEC 12 T3N R7E

EVIDENCE FOUND

NONE

