

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

$$\frac{1}{4} - \frac{14}{23}$$

Corner Code No. N-19

T 6 N, R 5 E, W.M.
Segregated Surveys:
Name: n/a

Corner Number: n/a

I. History of Corner Establishment and Subsequent Restoration:

Originally establish in 1909 by GLO Surveyor C. Frank Rhodes with an "X" marked on bedrock, and 2 BTs.

2. Description of Evidence Found:

"X" G.I. rock outcrop.
 1/4" marked north of "X".
 40" fir BT at N46W 32 feet, blown down, not chopped out.
 20" live hemlock BT at S15W 37 feet, not chopped out.

Aug 3 11 01

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 601.07A, Page No. 31. Date of work July 9, 1987.

Corner is the original GLO mark.

See reverse side for sketch.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973.
Date: August 3, 1987.

Signature H. Hanna Lush Certificate No. 21490



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered
and X. G. H.
Post
Funded
Mailed

County Auditor

G.L.O. of 1909, C. Frank Rhodes
West on true line bet 14 & 23

39.00 Enter green timber NW E SE
39.84 Cut X on bed rock, 6" above ground,
sloping SE for 1/4 corner and marked
1/4 North of cross, from which
38" fir N 40W 49L
8" Hem. S 15W 56L
11.01 Ch. Creek 15L wide N 70W.

1/4 Section Corner 11/2 Ten R SE

EVIDENCE FOUND:

"X AND 1/4" SCRIBED INTO ROCK OUTCROP
10" Fir 1/2 down N 40W 32 FT
20" Live Hemlock S 15W 37 FT (did
not chop out face)

CORNER IS AN X MARKED TO ROCK
OUTCROP BY G.L.O. SURVEYOR.

79.87

COPIED BY
BRASSER
HALLIN

31
801.07A

