

LAND CORNER RECORD

SKAMANIA County
T 4 N, R 9 E, W.M. Corner Code No. A-21
Segregated Surveys:
Name: Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ESTABLISHED BY DEPUTY SURVEYOR JACOB RICHARDSON
UNDER HIS CONTRACT No. 383, DATED OCTOBER/NOVEMBER 1892.
SET POST FROM WHICH BEARS:
7" FIR, S 12° 30' E, 40 IKS, MARKED "T4N R9E S1BT"
6" FIR, S 53° 30' W, 5 1/2 IKS, " " "T4N R9E S2BT"
6" FIR, N 14° 45' W, 13 1/2 IKS, " " "T4N R9E CC S1+2BT"

2. Description of Evidence Found:


NO REMAINS OF OLD EVIDENCE FOUND.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

10 Page No. 8 Date of work 7-87
SET STANDARD FOREST SERVICE 2 1/2" x 30"
ALUMINUM PIPE/CAP 24" IN THE GROUND, FROM
WHICH BEARS:

13" W. FIR, N 57° 30' W, 40.0 FT, SCRIBED "S35BT"
15" D. FIR, S 23° 15' W, 27.8 FT, " " "S2CCBT"
26" D. FIR, S 43° 30' E, 44.4 FT, " " "S1CCBT"

TREES HAVE RED PAINTED BANDS, TAGS
AND BRASS "PLS 18731" WASHERS. SET CARBONITE
GUARD POST NEAR MONUMENT.



FILED FOR RECORD
SKAMANIA CO. OREGON
BY TERRA SURVEYING

Washington Plane Coordinates: Zone, Y. Oct 27 2 53 PM '87
Order Accuracy. Derived From: A. D. Gaylord
Pin Pointed on Photo No. Date Located AUDITOR
MARY M. OLSON

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction in compliance with the provisions of Chapter
50, Laws of 1973. Date 8/87

Signature A. D. Gaylord Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In
Book of at page at the request of

County Auditor

Registered S
Indexed, in
Filed
Mailed