

LAND CORNER RECORD

T 4 N, R 9E, W.M.
Segregated Surveys:
Name: _____
County: SKAMANIA
Corner Code No. AB-21
Corner No.: _____
DLC, HES, Frac, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

NONE.

2. Description of Evidence Found:

NONE

FILED FOR RECORD
SKAMANIA CO. FARM
BY TERRA SURVIVING


OCT 27 2 54 PM '87
J. Dub, Dep.
AUDITOR
CARYN OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 10 Page No. 20 Date of work 7-37

SET RAILROAD SPIKE FOR CORNER
NEAR CENTERLINE OKLAHOMA ROAD. SET
REFERENCE MONUMENT WEST ON PROPERTY
LINE IN NORTH TOP OF DITCH BANK IN
12"x18" MOUND OF STONE. FROM SPIKE BARS, (S18731)
19" O. FIR, N 52°-15' W, 31.4 FT., SCRIBED
"S2 1/16 80 BT"

25" O. FIR, S 62°-45' E, 37.4 FT., SCRIBED "S1 1/16 80 BT"
2 1/2"x30" ALUMINUM PIPE/CAP, N 89°-53'-07" W, 50.00 FT.

TREES HAVE RED PAINTED BANDS, 54-3, 54-9 TAGS, AND
BRASS "PLS 18731" WASHERS. SET CARSONITE GUARD POST @
NORTH SIDE OF ROAD.



Washington Plane Coordinates: _____ Zone, Y _____, X _____
Order Accuracy. Derived From: _____
Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction in compliance with the provisions of Chapter
50, Laws of 1973. Date 9/18/87

Signature _____

Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this _____ day _____ 19____ at _____ M. In
Book _____ at page _____ at the request of _____

County Auditor

Registered S
Indexed, Sir
Filed
Mailed