

LAND CORNER RECORD

SKAMANIA County
T 4 N, R 9E, W.M. Corner Code No. C-17
Segregated Surveys:
Name: _____ Corner No.: _____
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Township.

1. History of Corner Establishment and Subsequent Restoration:

CORNER WAS ESTABLISHED BY DEPUTY SURVEYOR JACOB RICHARDSON UNDER HIS CONTRACT No. 383, OCTOBER/NOVEMBER 1892, SET POST FROM WHICH BEARS:
6" FIR, S50°W, 251KS., MARKED "1/4 SBT"
10" FIR, S38°E, 221KS., " " "1/4 SBT"

2. Description of Evidence Found:


NO ORIGINAL EVIDENCE FOUND.

FILED FOR RECORD
SKAMANIA T. 4 N. R. 9 E. S. 34
BY TERRA SURVING

OCT 27 3 52 PM '87
J. D. [unclear], Dep.
AUDITOR
CARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 10 Page No. 36 Date of work 7-87

SET STANDARD 2 1/2" x 30" FOREST SERVICE ALUMINUM PIPE/CAP 24" IN THE GROUND FROM WHICH BEARS:
5/8" x 30" IRON ROD, N0°19'-02"W, 10.96 FT.
5/8" x 30" IRON ROD, N85°10'-11"E, 35.51 FT.
IRON RODS HAVE PLASTIC "PLS 18731" CAPS.
NO TREES AVAILABLE, CORNER IS IN CLEARCUT.
SET CARBONITE GUARD POST NEAR MONUMENT.



Washington Plane Coordinates: _____ Zone, Y _____, X _____
Order Accuracy. Derived From: _____
Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 59, Laws of 1973. Date 8/87

Signature _____ Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M. In Book _____ of _____ at page _____ at the request of _____

County Auditor

Registered 5
Indexed, Jir
Indexed (2)
Filed
Mailed