

LAND CORNER RECORD

SKAMANIA County  
T 4 N, R 9E, W.M. Corner Code No. C-20/21  
Segregated Surveys:  
Name: \_\_\_\_\_ Corner No.: \_\_\_\_\_  
D.L.C. RES Tract, Mining Claim, Indian Allotment, Federal Reserve, Township.

1. History of Corner Establishment and Subsequent Restoration:

NONE.

FILED FOR RECORD  
SKAMANIA CO. ASH  
BY TERRA SURVEYING

OCT 27 4 18 PM '87

2. Description of Evidence Found:

NONE.

J. J. New, Rep.  
AUDITOR  
GARY M. ALLEN

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. \_\_\_\_\_

10 Page No. 26 Date of work 7-87

SET STANDARD 2 1/2" x 30" FOREST SERVICE  
ALUMINUM PIPE/CAP 24" IN THE GROUND, AT  
THE SOUTH BASE OF A 37" D. FIR, IN AN  
18" x 12" x 6" MOUND OF STONE, FROM WHICH BEARS:  
19" D. FIR, N41-15E, 21.7 FT., SCR'ED "52' 1/4 BT"  
20" D. FIR, S 7-30W, 32.7 FT., " "52' 1/4 BT"  
TREES HAVE RED PAINTED BANDS, TAGS, AND  
BRASS "PLS 18731" WASHERS. SET CARSONITE  
GUARD POST NEAR MONUMENT



Washington Plane Coordinates: \_\_\_\_\_ Zone, Y, \_\_\_\_\_, X, \_\_\_\_\_

Order Accuracy. Derived From: \_\_\_\_\_

Pin Pointed on Photo No. \_\_\_\_\_ Date \_\_\_\_\_ Located at \_\_\_\_\_

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 8/87

Signature Roy O. Gaylor

Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this \_\_\_\_\_ day of \_\_\_\_\_ 19\_\_\_\_ at \_\_\_\_\_ M. In Book \_\_\_\_\_ of \_\_\_\_\_ at the request of \_\_\_\_\_

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section \_\_\_\_\_ Chapter 50, Laws of 1973.

Registered S  
Roy O. Gaylor  
Auditor  
18731