

LAND CORNER RECORD

SKAMANIA County
T 5 N, R 9 E, W.M. Corner Code No. 2 23
Segregated Surveys: Corner No.:
Name: DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ESTABLISHED BY DEPUTY SURVEYOR JACOB RICHARDSON
UNDER HIS CONTRACT NO. 383, OCTOBER/NOVEMBER 1892, SET POST
FROM WHICH BEARS:
16" FIR, N 47° 30' W, 41KS, MARKED "SC 1/4 SBT"
18" FIR, S 22° E, 341KS, " "SC 1/4 SBT"

FILED FOR RECORD
BY TERRA SURVEYING

2. Description of Evidence Found:

NO REMAINS OF OLD EVIDENCE FOUND.

OCT 28 9 52 AM '87
J. New, Dep.
AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 10, Page No. 8, Date of work 7-87


SET STANDARD FOREST SERVICE 2 1/2" x 30"
ALUMINUM PIPE/CAP 24" IN THE GROUND, FROM
WHICH BEARS:

5/8" x 30" IRON ROD N 64° 45' E, 13.1 FT.

5/8" x 30" IRON ROD S 44° 30' W, 20.1 FT.

IRON RODS HAVE PLASTIC "TERRA-PLS 18731"
CAPS.

SET CARSONITE GUARD POST NEAR MONUMENT.
CORNER FALLS IN NEW CLEARCUT, NO SUITABLE
TREES AVAILABLE.



Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:
Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
under my direction, in compliance with the provisions of Chapter
50, Laws of 1973, Date 9/87 18731

Signature

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In
Book of at page at the request of

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section
Chapter 50, Laws of 1973.

Registered S
Indexed, Dir
Indirect
Filed
Mtd.