LAND CORNER RECORD

I, R. 7E , W.M. Corne ed Surveys: One-quarter DLC, HES, Tract, Mining Claim, Indian Allotment, Federal or of Corner Establishment and Subsequent Restoration s corner was originally set by Deputy Robert F. Warract No. 600. Larch post 14" Hemlock N25E-42 lks. iption of Evidence Found: rched for not found-the corner was probably destruct 50 years ago.	n: Whitham in 1903 under
y of Corner Establishment and Subsequent Restoration s corner was originally set by Deputy Robert F. was tract No. 600. Larch post 14" Hemlock N25E-42 lks. iption of Evidence Found: rched for not found-the corner was probably destr	ral Reserva, Townsite. 1: Whitham in 1903 under
y of Corner Establishment and Subsequent Restoration s corner was originally set by Deputy Robert F. Waract No. 600. Larch post 14" Hemlock N25E-42 lks. iption of Evidence Found: rched for not found-the corner was probably destr	ral Reserva, Townsite. 1: Whitham in 1903 under
s corner was originally set by Deputy Robert F. W tract No. 600. Larch post 14" Hemlock N25E-42 lks. iption of Evidence Found: rched for not found-the corner was probably destr	Whitham in 1903 under
tract No. 600. Larch post 14" Hemlock N25E-42 lks. iption of Evidence Found: rched for not found-the corner was probably destr	
rched for not found-the corner was probably destr	royed by wildfire
	royed by wildfire
생물하는 물리 그렇게 되었다. 그 사람들은 사람들이 되었다. 생물을 가는 물건을 하는 것이 되었다. 그렇게 되었다. 그렇게 되었다. 생물을 하는 물건을 하는 것이 되었다. 그렇게 되었다.	
인도 이 살 가고에서 말한 경험하는 것 같은 것 같은 경험을 하는 것으로	
ibe Monument, Accessories and Corollary Data to Perpe	etuate this Corner Location Dia-
corner and indicate meridian and reference to map of remaining Page No	record Surveyor's Field Book No.
2½"x30" Alum. pipe with a צאי Alum. cap צני in 'g	ground to bedrock stamped:
Bearing Trees: D-Fir N71½W-12.5' scribed ½S31BT Hemlock N12½W-10.3' scribed ½S31BT spike in base of 14" D-Fir S75E-15.0' to spike.	T4n R7E 831 1/4
n BT's have a 1" Brass disk stamped LS 16337.	Т3N 1987
guard posts East & West with decals 54-2 & surve	ey marker. LS 16337
led 54-9 & BT signs to BT's & painted band & blaz	zes red.
	AS AS PA
nington Plane Coordinates: Zone, YZone, Y	, x : 5 = 5
Order Accuracy. Derived From:	ω ≫ Σ _
Pointed on Photo No Date Located	d at
SURVEYOR'S CERTIFICATE	S
corner record correctly represents work performed by r	me or
r my direction in compliance with the provisions of Chaws of 1973. Date 9/22/97	napter
- D. Busay 16337	
Certificate No	
이 어린에 많이 많아야 되었다면서 뭐 하다고 하시 그렇던데? 다른 회사는	
 1. The Control of the C	1 12:05
AUDITOR'S CERTIFICATE	1120
for record this day of	
	. 19 at
for record this day of at page.	19. atM. InRegistered
for record this day of at page.	at the request of Registered County Auditor Indirect