

104730

State of Washington
DEPARTMENT OF NATURAL RESOURCES
BUREAU OF SURVEYS AND MAPS
LAND CORNER RECORD

1/4
13 | 18

Skamania County

T 2 N, R 5 E, W.M.

Corner Code No. L-1

Segregated Surveys:

Name: n/a

Corner Number: n/a

1. History of Corner Establishment and Subsequent Restoration:

Originally established by GLO in 1857 with a post and two bearing trees. Subsequently restored with a 2" iron pipe by persons unknown.

2. Description of Evidence Found:

2" iron pipe.

1965 DNR reference tag.

FILED FOR RECORD
SKAMANIA CO. WASH
BY DNR

FEB 22 2 21 PM '88

J. D. News, Dep.
AUDITOR
GARY M. OLSON

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location.
Diagram corner and indicate meridian and reference to map of record. Surveyor's Field
Book No. 600.29, Page No. 2. Date of work January 20, 1988.

Corner is a DNR aluminum cap
epoxied into found pipe.

See reverse side for corner diagram.

Pin Pointed on Photo No. _____, Date _____, Located at _____.

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work
performed by me or under my direction in compliance
with the provisions of Chapter 50, Laws of 1973.
Date: February 17, 1988.

Signature

H. Thomas Laird Jr.

21490

Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this _____ day of _____ 19____ at _____ M.
In Book _____ of _____ at page _____ at the request
of Washington State Department of Natural Resources.

Registered S
Indexed Dir
County Auditor Direct
Filed 2
Mailed _____

1-20-88

Laird

600.2

GLO Survey
 40.00 Set post -
 12" hemlock S52E 6 Links
 4" vine maple N67W 45 Links

T2N
 R4E
 S13T
 S18
 1988

1/4 corner 13+18 T2N R4E

No orig. evidence found.

Found 2" iron pipe in fence line (E-W)


1 1963 DNR RP

Other Surveys:

Germanson Book 2, pg 114 Skamania Co.

Hagedorn Book 12, pg 190 Clark Co.

BPA - 1938



BOOK 2/5 PAGE 43