

LAND CORNER RECORD

T. 4 N, R. 9E, W.M. County SKAMAHIA
Segregated Surveys: Corner Code No. H-14/15
Name: Corner No.:
D.L.C., HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

THIS CORNER WAS ESTABLISHED IN 1987 BY TERRA SURVEYING AS SHOWN IN BOOK 4/9 AT PAGE 118. UNDER CORNER CODE NUMBER H-13/14.

2. Description of Evidence Found:

BOTH ESTABLISHED BEARING TREES HAD BLOWN OVER IN THE WINTER STORMS. THE MONUMENT & GUARD POST AS SHOWN BELOW WERE IN EXCELLENT SHAPE.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 10 Page No. 40 Date of work 4/1988

FROM EXISTING MONUMENT A 16" DOUG FIR BEARS N 20-30 W, 59.9' SCRIBED "S 10 1/64 BT".

AN IRON ROD, 5/8" X 30", WITH PLASTIC CAP BEARS N 20-30 W, 13.33'.

A 15" DOUG FIR BEARS N 77-15 W, 25.36' SCRIBED "S 10 1/64 BT".

AN IRON ROD, 5/8" X 30", WITH PLASTIC CAP BEARS N 77-15 W, 25.36'.

PLASTIC CAPS ARE MARKED "TERRA LS 18731".

TREES HAVE RED PAINTED BANDS, TAGS AND BRASS "LS 18731" WASHERS. CARSONITE GUARD POST IS ALONG SIDE MONUMENT.

Washington Plane Coordinates: Zone, Y, X.
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date. Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date APRIL 12, 1988

Certificate No. 18731



AUDITOR'S CERTIFICATE

FILED FOR RECORD BY TERRA SURVEYING APR 14 11 40 AM '88
AUDITOR GARY OLSON
This corner record was filed for record this day of 19 at M. In of at page at the request of.

County Auditor