

LAND CORNER RECORD

T. S N, R. 9E, W.M. County SKAMANIA
 Segregated Surveys: Corner Code No. Z-15
 Name: Corner No.:
 D.L.C., H.E.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:


CORNER ESTABLISHED by DEPUTY SURVEYOR JACOB RICHARDSON
 UNDER CONTRACT No 383, OCTOBER, 1892. SET POST
 FROM WHICH BEARS:
 18" FIR, N 39W, 12 LKS, MARKED "SC 1/4 S BT"
 15" FIR, S 8-30 E, 38 LKS, MARKED "SC 1/4 S BT"

2. Description of Evidence Found:

NO REMAINS OF GLO EVIDENCE FOUND.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

Page No. 24 Date of work 7-27-87
 SET STANDARD FOREST SERVICE 2 1/2" x 30" ALUMINUM PIPE 1/2" CAP.
 24" IN THE GROUND FROM WHICH BEARS:
 5/8" x 30" IRON ROD, N 23-00E AT 11.70'
 5/8" x 30" IRON ROD, S 49-45E, 4.80'
 RODS HAVE PLASTIC CAP "TERRA LS18731"



FILED FOR RECORD
 SKAMANIA CO WASH
 BY TERRA SURVEYING


APR 14 11 59 AM '88

AUDITOR
 GARY H. OLSON

Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date. Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
 under my direction in compliance with the provisions of Chapter
 50, Laws of 1973. Date APRIL 12 1988
 Signature Roy O. Gaylord Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this. day of. 19. at. M. In
 Book. of. at page. at the request of.

County Auditor

Registered 5