

LAND CORNER RECORD

T. S. N. R. 9E, W.M. County
 Segregated Surveys: Corner Code No. 7-19
 Name: Corner No.:
 D.L.C., I.R.S., Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ESTABLISHED by DEPUTY Surveyor JACOB RICHARDSON UNDER CONTRACT NO 383, OCTOBER, 1892.
 SET POST FROM WHICH BEARS:
 6" FIR, SSW, 23 LKS. SCRIBED "SC 1/4 SBT"
 14" FIR, N 18-30E, 71 LKS, SCRIBED "SC 1/4 SBT"


2. Description of Evidence Found:

1/2" IRON SPIKE, UNKNOWN ORIGIN, FROM WHICH:
 6" Doug FIR, Now 26" Doug fir, BEARS SSW, 15.1', HEALED BLAZE
 14" " " , Now 41" " " , " N 18-30E, 46.86', HEALED BLAZE

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location Diagram corner and indicate meridian and reference to record. Surveyor's Field Book No.

Page No. 6 Date of work 3-23-81
 SET STD 2 1/2" X 30" ALUMINUM PIPE AND CAP, 24" IN
 THE GROUND FROM WHICH
 17" Doug fir BEARS S12W, 14.15', SCRIBED "S2BT"
 22" Doug fir BEARS N 79-30E, 5.35',
 SCRIBED "1/4 S35 SC BT"

Trees are painted, signed and have
 BRASS WASHERS "PLS 18731." SET GUARD
 POST WITH PROPER CONTRACT SIGNS.
 PLACED SPIKE IN HOLE WITH MONUMENT



Washington Plane Coordinates: Zone, Y, X
 Order Accuracy. Derived From:
 Pin Pointed on Photo No. Date. Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or
 under my direction in compliance with the provisions of Chapter
 50, Laws of 1973. Date APR 12 1981
 Signature: [Signature] Certificate No. 18731



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In
 Book of at page at the request of

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5
 Chapter 50, Laws of 1973.

FILED FOR RECORD
 BY TERRY
 SURVEYING
 APR 14 12 01 PM '81
 AUDITOR
 GARY M. OLSON