

LAND CORNER RECORD

T. S. N. R. 9E, W.M. County SKAMANIA
Segregated Surveys: Corner Code No. Z-21
Name: Corner No.:
D.L.C., HKS, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

CORNER ESTABLISHED BY DEPUTY SURVEYOR JACOB RICHARDSON UNDER CONTRACT NO 383, OCTOBER, 1892, SET POST FROM WHICH BEARS:
9" MAPLE, N 38-30E, 43 LKS, SCRIBED TSN, R9E, 536 BT.
20" FIR, N 23-30W, 23 LKS, SCRIBED TSN, R9E, 535 BT
10" FIR, S 56-30W, 9 LKS, SCRIBED TSN, R9E, SC 35+36 BT

2. Description of Evidence Found:

20" Doug FIR, NW 35" IN GOOD Condition with visible BLAZE
OTHER BTS GONE.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work.


SET STD. FOREST SERVICE 2 1/2" X 30" ALUMINUM PIPE & CAP, 24" IN THE GROUND FROM WHICH BEARS:

35' Doug FIR N 23-30W, 15.18' with HEALED GLO BLAZE

32" Doug FIR N 83-30E, 10.53', SCRIBED "5 36 SCBT"

15" HEMLOCK S 8-30E, 54.10', SCRIBED "T4N S2 BT"


TREES HAVE RED PAINTED BANDS, TAGS AND BRASS WASHERS "PLS 18731", SET CAISONITE POST NEAR MONUMENT



Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:
Pin Pointed on Photo No. Date. Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date APR 12, 1988
Signature: [Signature] Certificate No. 18731



AUDITOR'S CERTIFICATE

day of 19 at M. In
of at page at the request of.

County Auditor

FILED FOR RECORD
BY JEROME
APR 14 12 06 PM '88
AUDITOR
GARY M. OLSON