

106177

BOOK 6/6 PAGE 36

# LAND CORNER RECORD

HAMPSTUR CORPORATION  
1010 Douglas A3  
LONGVIEW, WASHINGTON 98632


T 6 N, R 6 E. \_\_\_\_\_ W.M. \_\_\_\_\_ County SKAMANIA  
Segregated Surveys: \_\_\_\_\_ Corner Code No. F-8 (WC)  
Name: \_\_\_\_\_ Witness Corner to NE.1/16 cor. Section 8 Corner No.: \_\_\_\_\_  
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:  
In 1977, Hagedorn, Inc. set a 5/8" rebar and referenced 3 trees for the true NE.1/16 corner, as indicated on their survey map recorded in BOOK 1 of SURVEYS at PAGE 142, with Skamania County. In 1985, Hagedorn, Inc. established the Witness Corner, as shown in the diagram below, and indicated on their survey map recorded in BOOK 2 of SURVEYS at PAGE 236, with Skamania County. Then on July 26, 1988, HAMPSTUR CORP. found and maintained the above mentioned Witness Corner, as shown below, while working on a corner restoration project for PLUM CREEK TIMBER CO., under the direction of C. Hampton, LS. #18,087.

2. Description of Evidence Found:  
-Found the USFS aluminum monument as set in 1985, as mentioned above and shown below.  
-Found both scribed references, one blown over, as scribed in 1985 and shown below.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 1985 RP  
PS-056 Page No. 17 Date of work 7-26-1988

- LOCATION:
- on a 75% Southwest slope.
  - on a small bench, 75 ft. North of the jct. of 2 creeks.
  - approx. N55°E--150 ft. from the Northeast corner of a large rock slide.
  - approx. 100 ft. West of the Southeast corner of timber stand.
  - found a USFS posted line running to the East and to the West,



Washington Plane Coordinates: \_\_\_\_\_ Zone, Y \_\_\_\_\_ X \_\_\_\_\_  
Order Accuracy. Derived From: \_\_\_\_\_  
Pin Pointed on Photo No. \_\_\_\_\_ Date \_\_\_\_\_ Located at \_\_\_\_\_

## SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date October 19, 1988

Signature Calvin J. Hampton LS. #18,087  
Certificate No



## AUDITOR'S CERTIFICATE

Filed for record this \_\_\_\_\_ day of \_\_\_\_\_ 19\_\_\_\_ at \_\_\_\_\_ M. In \_\_\_\_\_ of \_\_\_\_\_ at page \_\_\_\_\_ at the request of \_\_\_\_\_  
County Auditor \_\_\_\_\_  
Registered \_\_\_\_\_  
Ind. J. W. \_\_\_\_\_  
In-ct \_\_\_\_\_  
F. \_\_\_\_\_  
M. \_\_\_\_\_

Record prepared by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

FILED FOR RECORD  
SKAMANIA COUNTY WASH  
BY HAGEDORN CORP  
NOV 14 3 40 PM '88  
GARY M. OLSON