

LAND CORNER RECORD

T. 7 N, R. 10E, W.M. County SKAMANIA
Segregated Surveys: Corner Code No. Z-17
Name: SOUTHEAST SECTION CORNER SECTION 34 Corner No.:
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:
THE CORNER WAS ESTABLISHED BY NEWTON CLARK IN 1882 AND WAS COMMON FOR SECTIONS 2, 3, 34 AND 35. IN 1917 ROY CAMPBELL MADE A SEPARATE CORNER GOOD FOR SECTIONS 34 AND 35 ONLY, DESTROYING ANY REFERENCES AT THE OTHER CORNER FOR SECTIONS 34 AND 35.

2. Description of Evidence Found:
FOUND THE 2" BRASS BAP, FIRMLY SET, AS DESCRIBED BY ROY CAMPBELL.

33" ROTTEN STUMP N27 W 111°
VISIBLE SCRIBING (T7N R10E S34 BT)

43" PONDEROSA PINE N35 E 103°
VISIBLE SCRIBING (7N 10E S35 B)

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. BOOK III Page No. 10 Date of work 10-88

BT#1 17" PONDEROSA PINE SCRIBED T7N R10E S35 BT
N53-11-37E 40° BRASS WASHER LS2234B

BT#2 9" FIR SCRIBED T7N R10E S34 BT
N47-19-53W 19° BRASS WASHER LS2234B

ALL BEARING TREES HAVE A 6" BAND AND
BLAZE PAINTED RED WITH A 54-3 ATTACHED
TO THE FRONT OF THE TREE AND A 54-4 ATTACHED
TO THE BACK

Washington Plane Coordinates: Zone, Y, X
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Dec 1, 1988

Signature John E. Richmond Certificate No. 2234B



AUDITOR'S CERTIFICATE

Filed for record this 5 day of May 1989 at 11:31 A.M. In Book 7/10 of Monuments at page 1 at the request of

John E. Richmond
Gary M. Olson
County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.