



107751

BOOK 6/6 PAGE 59

LAND CORNER RECORD

HAMPSTUR CORPORATION
1010 Douglas A3
LONGVIEW, WASHINGTON 98632

T 6 N, R 6 E., W.M. SKAMANIA County
Segregated Surveys: Corner Code No. L-1
Name: W. 1/4 corner of Section 18 Corner No.: _____
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

This corner was originally a 15"x12"x6" boulder, as set in 1909 by C.F. Rhodes under GLO contract #674. Then in 1984, B.L. Jones, LS #18,734, remonumented the corner with a standard 2 1/2" USFS Aluminum mon. and added additional references while under a USFS contract. Then on August 17, 1988, R. Bogdon, (from HAMPSTUR CORP.), located the above corner and refreshed the RP's and added a steel reference post as indicated in the diagram below, while working on a "corner restoration" project for PLUM CREEK TIMBER COMPANY, under the direction of C. Hampton, PLS #18,087.

2. Description of Evidence Found:

1909 GLO MONUMENT: found the aluminum monument set in 1984 in place of the original stone, as mentioned above and shown in the diagram below.

ORIGINAL GLO BT's:

-50" Fir, S130E--28 lks.; found a 56" live tree, with over grown face--see diagram.
-38" Fir, N640W--25 lks.; found a 40" Fir snag, 50 ft. high--see diagram below.

SUBSEQUENT RESTORATION:


Found the aluminum monument as set in 1984 along with 2 references, as mentioned above and shown in the diagram below.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No.

PS-056 Page No. 36 Date of work 8-17-88

LOCATION:

- on a 20% Northwest slope.
- 75 ft. East of a creek, which bears Northeast.
- at the existing NE corner of approx. 6 yr. old reprod.
- a USFS posted line leads to the North and to the West.



Washington Plane Coordinates: _____ Zone, Y _____ X _____
Order Accuracy. Derived From: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 28, 1989

Signature Calvin J. Hampton, PLS

LS #18,087
Certificate No



AUDITOR'S CERTIFICATE

Book 6/6 Page 59 day of _____ 19____ at _____ M. In _____
of _____ at page _____ at the request of _____

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

Registered
Indexed, Jir
Indirect
Filed 9-1-89
Mailed