

107754

BOOK 6/5 PAGE 37

# LAND CORNER RECORD

HAMPSTUR CORPORATION  
1010 Douglas A3  
LONGVIEW, WASHINGTON 98632

T 6 N.R. 5 E. \_\_\_\_\_, W.M. \_\_\_\_\_ SKAMANIA County  
Segregated Surveys: \_\_\_\_\_ Corner Code No. L-25  
Name: E. 1/4 corner of Section 13 Corner No.: \_\_\_\_\_  
DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.


1. History of Corner Establishment and Subsequent Restoration:  
This corner was originally a 15"x12"x6" boulder, as set in 1909 by C.F. Rhodes under GLO contract #674. Then in 1984, B.L. Jones, LS #18,734, remonumented the corner with a standard 2 1/2" USFS Aluminum mon. and added additional references while under a USFS contract. Then on August 17, 1988, R. Bogdon, (from HAMPSTUR CORP.), located the above corner and refreshed the RP's and added a steel reference post as indicated in the diagram below, while working on a "corner restoration" project for PLUM CREEK TIMBER COMPANY, under the direction of C. Hampton, PLS #18,087.

2. Description of Evidence Found:  
1909 GLO MONUMENT: found the aluminum monument set in 1984 in place of the original stone, as mentioned above and shown in the diagram below.  
ORIGINAL GLO BT's:  
-50" Fir, S13°E--28 lks.; found a 56" live tree, with over grown face--see diagram.  
-38" Fir, N64°W--25 lks.; found a 40" Fir snag, 50 ft. high--see diagram below.  
SUBSEQUENT RESTORATION:  
Found the aluminum monument as set in 1984 along with 2 references, as mentioned above and shown in the diagram below.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. PS-056 Page No. 36 Date of work 8-17-88

**LOCATION:**

- on a 20% Northwest slope.
- 75 ft. East of a creek, which bears Northeast.
- at the existing NE corner of approx. 6 yr. old reprod.
- a USFS posted line leads to the North and to the West.



Washington Plane Coordinates: \_\_\_\_\_ Zone, Y \_\_\_\_\_ X  
Order Accuracy. Derived From: \_\_\_\_\_

Pin Pointed on Photo No. \_\_\_\_\_ Date \_\_\_\_\_ Located at \_\_\_\_\_

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date August 28, 1989

Signature Calvin J. Hampton LS #18,087  
\_\_\_\_\_  
Certificate No



FILED FOR RECORD  
BY Hampstur Corp  
AUG 30 4 42 PM  
SKAMANIA CO. WASH.  
AUDITOR  
GARY H. OLSON

### AUDITOR'S CERTIFICATE

\_\_\_\_\_ day of \_\_\_\_\_ 19\_\_\_\_ at \_\_\_\_\_ M. In  
\_\_\_\_\_ of \_\_\_\_\_ at page \_\_\_\_\_ at the request of \_\_\_\_\_

County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

Registered \_\_\_\_\_  
Indexed, dir \_\_\_\_\_  
ndirect \_\_\_\_\_  
Filed 9-1-89  
Mailed \_\_\_\_\_