State of Washington DEPARTMENT OF NATURAL RESOURCES


CENTRAL REGION

1/4

LAND CORNER RECORD

Skamania County 7 3 N, R 9E, W.M. Segregated Surveys: Name: n/a Corner Code No. P-13 Corner Number: n/a History of Corner Establishment and Subsequent Restoration: Originally established by GLO in 1880 with a post and 2 BT's. Subsequently restored by Skamania County with an iron pipe with brass cap. 2. Description of Evidence Found: 1" iron pipe with stamped brass cap. Fir stub BT at S56W 5.3 feet with visible scribing. Hemlock stub BT at S67E 8.6 feet with axe marks. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 500,31, Page No. 76. Date of work 8-29-90. Corner is a Skamania County iron pipe with stamped brass cap. See reverse side for sketch. Washington Plane Coordinates: Not tied Derived from: Pin Pointed on Photo No. Located at SURVEYOR'S CERTIFICATE [Seal] This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: October 29, 1990. Signature Certificate No. AUDITOR'S CERTIFICATE Filed for record this _______ day of November of Washington State Department of Natural Resources. 19 90 . at 1/2" at page 44

County Additor S County Addition S Cou



BOCK 3/9 PAGE 45

