BOOK 3/9 PAGE 48

State of Washington DEPARTMENT OF NATURAL RESOURCES CENTRAL REGION

LAND CORNER RECORD

Skamania County

T 3 N, R 9E, W.M. Segregated Surveys: Name: n/a

Corner Code No. N-15

Corner Number: n/a

History of Corner Establishment and Subsequent Restoration:

Originally established by GLO in 1880 with a cedar post and 2 BT's. Subsequently restored in 1989 by Roy Gaylord, LS 18731, with a 1" iron pipe with stamped brass cap.

Description of Evidence Found:

Above described pipe and cap. 24" fir stump at N62E 8.5 feet with axe marks and scribing.

Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 600.31, Page No. 75. Date of work 9-20-90.

Corner is an iron pipe with stamped brass cap.

See reverse side for sketch.

Washington Plane Coordinates: N 147979.005 E 1340064.945 NAD 83, US Feet Derived from: Global Positioning Satellite System, direct occupation. Pin Pointed on Photo No. _ ____, Date

SURVEYOR'S CERTIFICATE

[Seal]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date: October 29, 1999.

Kona Zaud Signature

Certificate No.


AUDITOR'S CERTIFICATE

Filed for record this day of In Book of Washington State Department of Natural Resources. of

19 90 at the request

Olson County Auditor

Segistered Indexed, Dir ladirect File ed



BOOK 3/9 PAGE 49

