


**OLSON** LAND SURVEYORS  
ENGINEERS  
ENGINEERING INC. 1111 BROADWAY, VANCOUVER, WA 98660



# LAND CORNER RECORD

T. 2N, R. 5E, W.M.  
Corner Code No. X-13  
SKAMANIA County

Segregated Surveys:  
Survey Tract Name: \_\_\_\_\_  
(D.A.C., U.S. Mining Claim, Indian Allotment, Federal Reserve, Townsite.)  
Corner No. or Name: EAST 1/4 CORNER SEC. 33

## 1. History of Corner Establishment, Subsequent Restoration and Description of Evidence Found:

The original corner post was established in 1859 by U.S. Deputy Surveyor Lewis Van Vleet.

Bearing trees were a 12" maple South 77° West, 28 links and an 18" maple South 65° East, 17 links of which no evidence remains. This corner was calculated by single proportion during previous survey 1-211.

## 2. Description of Monument, Accessories and Corollary Data Set to Perpetuate this Corner Location.

Diagram corner and indicate meridian and reference to map of record, Surveyor's Field Book No., Page No., and Date of work.

FILED FOR RECORD  
SKAMANIA COUNTY WASH  
BY Olson Engineering

JUL 3 4 03 PM '91

P. Lowrey  
GARY M. OLSON

|              |          |
|--------------|----------|
| Registered   | <u>/</u> |
| Indexed, Dir | <u>/</u> |
| Indirect     | <u>/</u> |
| Filmed       | <u>/</u> |
| Mailed       |          |

Washington Plane Coordinates:


Zone \_\_\_\_\_ Y \_\_\_\_\_ X \_\_\_\_\_  
Order Accuracy. Derived From \_\_\_\_\_

Pin Pointed on Photo No. \_\_\_\_\_ Page No. \_\_\_\_\_ Located at \_\_\_\_\_

### SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of RCIV 58:09 and WAC 332.

[Signature] 9025  
Signature Certificate No.



### AUDITOR'S CERTIFICATE

Filed for record this 3rd day of July at 4:03 P.m. in book 2/5 of Land Corner Records at Page 58 at the request of P. Lowrey

JERRY C. OLSON

[Signature]  
Deputy County Auditor