FILED FOR RECORD SKAMANIA CO. WASH

BY RODET Glasser
LAND CORNER RECORD HAY 4 2,44, PM '93
OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT
TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON GARY M. OLSON THE BACK.) BOOK /35 PAGE
Corner Indexing Information.
TWP 2 North RGF 6 East Corner Code Z-11 (Willamette Meridian)
ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name,
South quarter of Section 33, Township 2 North, Range 6 East, Willamette Meridian.
Skamania County Washington: AUDITOR'S USE
Land SETVEYOR Information: (or Public Officer to per RCW 58.49.690)
This corner record correctly represents work performed by me or under by direction in conformance with the Survey Recording Act.
Company or agency:
Minister & Glaeser Surveying, Inc. 2208 E. Evergreen Blvd.
Vancouver, WA. 98661
Phone: (206) 694-3313
Fax: (206) 694-8410
AND ASCISTERED SUPPO
VALLANDS
EXPIRES 5-30-93
Signature // 100 Sea Date: 4-20-93 Seal: 15024
Signature Date: 4-20-93 Seal: /5024 Washington Plane Coordinates: N: E:
Order: Zone: Datum (Date of adjustment):
Corner Information: Use the space below to provide the following
information regarding the corner.
(1) Pertinent Corner History: The original survey was conducted by Deputy Surveyors Lewis
Wantiget and John Newsom, under Contract No. /. dated April 43
tock who enryer was performed between ADILL 29, and 30, 1007
Set a post 40.00 chains East from the Southwest corner of Section 33.
R.T's were as follows:
12" Diam. Maple, North 45° East, 14 Links 30" Diam. Fir, South 45° West, 3. Links
t meanway was conducted by Denuty Surveyor Charles E. Sears, unde
- ALLEGE MA 907 ASTAN NACOMNOT 21. INNEL THE BULVEY WG
performed between March 16 and June 26, 1883. They found remain of the quarter corner post in the ground and the bearing trees wer
mharafore a new post. 3 feet long and 3 inches squar
was set 24 inches into the ground, 40 chains East from th
Southwest corner of Section 33. B.T.'s were as follows:
12" Diam. Maple, North 45° 14 Links
30" Diam, Fir, South 45 West, 39 Links

(2) Evidence Found at the Corner:
No original evidence was found. Skamania County brass cap was accepted as the corner based on reputation and use.

(3) Corner Perpetuation Information:


Surveys

Book 2, Page 144 Book 1, Page
Book 2, Page 237

Short Plats

Book 1, Page 97

De girle	ed I
e lexed	Dir b
mirest	
Filmed	
Mailed	



RCW 58,09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d, corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENTS

FOUND 3" BRASS CAP.

STAMPED INFO. 14 COR. 33-2-6

14 COR. 4-1-6

33 SKAMAHIA COUNTY

30" HEMLOCK
"RP." AT 1.0 ABOVE
"GROUND IN SOUTH
"FACE OF TREE
(BLACE)

NOTE: PLACED ALUM. NAIL WITH PLASTIC TAG. MARKED GLAESER #15024 AT ALL R.P.'S

7.06

26" FIR
'RR" AT. ED ABOVE
GROUND ON WEST
FACE OF TREE
(BLAZE)

16" ALDER
"R.P" AT. 1.50 ABOVE GROUND
ON EAST FACE OF TREE
(BLAZE)