

FILED FOR RECORD
SKAMANIA CO. WASH
BY *Robert Glaeser*

MAY 4 2 51 PM '93

G. Lawry
AUDITOR
GARY M. OLSON

LAND CORNER RECORD

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY
OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT
TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON
THE BACK.)

116163

BOOK 135 PAGE 81

Corner Indexing Information:

TWP 1 North RGE 6 East Corner Code A-9
(Willamette Meridian)

ADDITIONAL IDENTIFIER: (e.g., BLM designation
for the corner, street intersection, plat name,
block, lot, etc.)

Northeast corner of Section 5, Township 1 North, Range 6 East,
Willamette Meridian.


Skamania County Washington:

AUDITOR'S USE

Land Surveyor Information: (or Public Officer as per RCW 58.09.090)

This corner record correctly represents work performed by me or
under by direction in conformance with the Survey Recording Act.

Company or agency:
Minister & Glaeser Surveying, Inc.
2203 E. Evergreen Blvd.
Vancouver, WA. 98661
Phone: (206) 694-3313
Fax: (206) 694-8410



Signature *Robert W. Glaeser* Date: 4-20-93 Seal: 15024

Washington Plane Coordinates: N: _____ E: _____
Order: _____ Zone: _____ Datum (Date of adjustment): _____

Corner Information: Use the space below to provide the following
information regarding the corner.

(1) Pertinent Corner History:

The original survey was conducted by Deputy Surveyors Lewis
VanVleet and John Newsom under Contract No. 7, dated April 29,
1859. Set a post for corner common to Sections 4, 5, 32 and 33,
80 chains East from the Northwest corner of Section 5.

B.T.'s as follows:

- 10" Diam. Chittum, North 65° West, 3 Links
- 15" Diam. Chittum, South 75° East, 18 Links
- 7" Diam. Dogwood, South 22° West, 51 Links
- 18" Diam. Maple, North 40° East, 54 Links

A resurvey was conducted by Deputy Surveyor Charles E. Sears
under Contract No. 287, Dated December 23, 1882. The survey was
conducted between March 16 and June 26, 1883.

A evidence of corner to Sections 4, 5, 32, and 33 was destroyed
by the clearing of land. Corner was re-established 80.00 chains
East of the Southwest corner of Section 32. Set a post 4 feet
long and 4 inches square, 24 inches into ground.

B.T.'s as follows:

Registered _____
Indexed, Dir _____
Indirect _____
Filmed _____
Filed _____

36" Diam. Fir, North 46°-30' East, 128 Links
 30" Diam. Fir, South 63° East, 170 Links

BOOK 135 PAGE 82

(2) Evidence Found at the Corner:

No original evidence was found.

Axle shaft was accepted as the corner based on reputation and use.

(3) Corner Perpetuation Information:


Surveys

Book 2, Page 237
 Book 2, Page 9

Book 1, Page 97

Short Plats

MARK THE CORNER LOCATION ON THE DIAGRAM BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE.



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENTS:

