. 120646

FILED FOR RECORD LAND CORNER RECORD SKAMAHIA CO. WASH BY Ko beet G. Deza. (THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL

SEP 27 3 51 PM '94 AUDITOR 0 GARY M. OLSON

BOOK 146 PAGE 60

RESCURCES, PURSUANT TO ROW 58.09. ALPHA-MINERIC INDEX DIAGRAM ON THE BACK)

CORNER INDEXING INFORMATION:

2N RGE 6E CORNER CODE

(Willamette Meridian)

(See instructions on back of LCR)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot. etc.)

CENTER QUARTER CORNER SECTION 21

COUNTY: SKAMANIA

LAND SURVEYOR INFORMATION: (or Public Officer as per ROW 58.09.090)

This corner record correctly represents work performed by $\mbox{\it me}$ or under $\mbox{\it my}$ direction in conformance with the Survey Recording Act.

COMPANY OR AGENCY: DEAN SURVEYING

ADDRESS.

ROBERT G. DEAN 7101 NE 74TH AVE VANCOUVER, WA 98662

Survey for Jim Combelic, Job #94091, in NE% Sec. 21, T 2 N, R 6 E, WM., Field Book Pages 21 & 22

WASHINGTON PLANE COORDINATES:

E :

ORDER:

ZONE:

DATUM (Date of adjustment):

CORNER INFORMATION: Use the space below to provide the following information regarding the corner: (1) Pertinent Corner History. (2) Evidence Found at the Corner, and (3) Corner Perpetuation Information. Please title and number the parts of your discussion accordingly. If additional space is needed use the back. (For (3), diagram the references. Also, provide the cross-reference to a map of record, if applicable, the surveyor's field back no./prge no., and the date of work.) (See the back of this form for the requirements of the Survey Recording Act.)

(1) Pertinent Corner History:

June 1965, Clark H. Eldridge, Skamania County Engineer, incomplete record of survey in Engineer's drawer 34-6.2-21.1. Set County Monument on 3/4" I.P.

November 1973, Wayne Main, Survey Book 1 Page 5, Found 3/4" Brass Cap N 69°57'19" W 118.587' from "Computed Section Center."

May 1978, William F. Hagedorn, Survey Book 1 Page 165, Set 5/8" Iron Rod, from

Found Iron Pipe and Brass Cap N 76°37' W 93.30'; Found 1" Iron Pipe bears S 45° 58' E 28.22'; 6" Alder N 64° W 32.11' 10" Fir N 74° E 33.74'; 40" Fir S 23° E 1.74'.

(2) Evidence Found at the Corner:

September 19, 1994 I measure to the location of the true center of Section 21, corner falls in 50" Fir, from which:

A 5/8" iron rod, with yellow plastic cap marked " HAGEDORN . RLS 9579", in hollow of 50" Fir, bears N 0°32' W 1.91';

A 3/4" galvanized iron pipe, with 3/4" brass disc stamped "W. MAIN & ASSOC" wired to the side. leaning East 0.2'±, bears \$ 50°06' E 27.00';

A 3/4" galvanized iron pipe, with 3½" brass cap marked as shown to left, loosely set, oriented South, bears N 76°35' W 93.47';

22" Douglas Fir, healed double scars, bears N 67°50' E 35.0';

16" Alder, southern-most in clump of three trees, 3/4" brass disc visible on face 4" deep, bears N 62°40' W 33.2'.


(see back page)

Registered Induced, Dir indirect Filmed

AUDITUR'S USE



Molled



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that may be helpful to relocate or identify the corner position.

SPACE FOR ADDITIONAL COMMENT:

Note: Bearings are based on solar observations. Distances are horizontal to centers of root crowns of bearing trees.

(3) Corner Perpetuation Information: None