

(THIS FORM PRESCRIBED BY THE PUBLIC LAND SURVEY OFFICE, DEPARTMENT OF NATURAL RESOURCES, PURSUANT TO RCW 58.09. ALPHA-NUMERIC INDEX DIAGRAM ON THE BACK.)

Nov 22 1 53 PM '95

R. Johnson

AUDITOR
GARY M. OLSON

TWP 1N RGE 5E CORNER CODE GH-10-11
(Willamette Meridian) (See instructions on back of LCR)

ADDITIONAL IDENTIFIER: (e.g., BLM designation for the corner, street intersection, plat name, block, lot, etc.)

123874

BOOK 153 PAGE 797

SKAMANIA


COUNTY:

.. AUDITOR'S USE

LAND SURVEYOR INFORMATION: (or Public Officer as per RCW 58.09.090)

This corner record correctly represents work performed by me or under my direction in conformance with the Survey Recording Act.

COMPANY OR AGENCY: BELL DESIGN CO.
P.O. BOX 1990
ADDRESS: 320 GREEN ST.
WHITE SALMON, WASH.
98672
509-423-3886



SEAL/SIGNATURE/DATE

WASHINGTON PLANE COORDINATES: N:


33

ORDER:

ZONE:

DATUM (Date of adjustment):

CORNER INFORMATION: Use the space below to provide the following information regarding the corner:
(1) Pertinent Corner History, (2) Evidence Found at the Corner, and (3) Corner Perpetuation Information.



Indexed, ☒
 Indirect ☒
 Filmed ☒
 Mailed ☒

JACK COLLINS SET WOODEN FENCE POST FOR NW
CORNER OF LOT HE SOLD TO BARRIE BURROWS
IN 1977 AS PER DEED IN BOOK 73 PAGE 146.
THIS IS NOT THE SAME CORNER SET BY THOMAS
IN 1977 AS PER SURVEY FOR COLLINS IN BOOK 1, PAGE 117.

DETERIATED WOOD IN GROUND BELONGING TO DOWN
FENCE POST SET BY COLLINS.

SET 18" x 9" REBAR WITH BELL DESIGN YELLOW
PLASTIC CAP AT SAME LOCATION AS FOUND
ROTTED OUT FENCE CORNER POST. SAID LOCATION
FITS WITH ADJACENT FOUND SURVEY MARKERS.
TIED Y.P. CAP TO TWO POWER POLES AS SHOWN
IN ABOVE DRAWING.

A 26x26 grid of small squares, likely a coordinate system for a map or chart. The grid is labeled with numbers 1 through 26 along the top and left edges. A small, dark, irregular shape is visible near the center of the grid, around the intersection of columns 10 and 11 and rows 10 and 11.

[illegible]

第 一 章 緒 論