## 800x 249 page 85

AUG 28 10 53 An '03 Odavny J. MICH

> दे भूति दे । ज्या स ednesd U Aditor; Pleant 10105

## LAND CORNER RECORD

GRANTOR/SURVEYOR/PUBLIC OFFICER: This corner record correctly represents work performed by me or under my direction, in conformance with the Survey Recording Ac

USDA Forest Service

ADDRESS:

Gifford Pinchot National Forest 10600 NE 51" Circle Vancouver WA 98682



Don Karsch Forest Land Surveyor

8/7/2003 Date

GRANTEF: PUBLIC SEAL/SIGNATURE/DATE CORNER CODE: H-10 TWP: 4 NORTH RGE: 7 EAST LEGAL: TWP: 4 NORTH RGE: / BAST CORNER CODE: N-10
ADDITIONAL IDENTIFIER: (BLM designation, street, or plat names, block, lot,

3N1/16 SEC 9

COUNTY: SKAMANIA
WASHINGTON PLANE COORDINATES: N:

ORDE/: ZONE: DATUM: (DATE OF ADJUSTICAT:
CORNIR INFORMATION: Discuss the history, evidence found, and perpetuation of the
corner. Diagram the references; provide the date of work; and if applicable, a
reference to a map of record and/or the field book/page no. Use the back, if needed.

Corner History:
This corner was originally established by Larry D. Bishop, PLS #16337 in May of 1982, and monumented with a 2 %" x 30" aluminum pipe with a 2 %" aluminum cap. He also marked 2 bearing trees:

11" D. Fir - S70°E, 21.2 ft. scribed "SW 1/16 S9" upper blaze and a lower blaze scribed "BT" 9" D. Fir - S38°E, 23.1 ft. scribed "SW 1/16 S9" upper blaze and a lower blaze scribed "BT"

On July 22, 2003 I found the corner monument in good condition set in mound of stones. ound Bishop BT's:

A 10" D. Fir with visible overgrown face blaze bears S70°E, 21.2 ft. A 9" D. Fir snag with visible face scribing bears S38°E, 23.1 ft.

## New ET's Established:

A 22" D.Fir bearing S20°E, 21.0' was scribed "SW 1/16 S9 BT"

Placed "BT" tags and "Land Survey Gonument" signs on all BT's. Painted 6" red band and faces on all Bt's.

Corner sits south and uphill from old dry creek bed, and sits in stand of 2<sup>nd</sup> growth Douglas Fir trees. Forest service property lies south and west of corner, and property lines leading east and north from corner are brushed, blazed, and posted w/USFS carsonite posts. Bearings are by compass w/ 18° East declination. Distances are to nail in side center of bearing tree.


Witnessed by: G. Wheatley, U.S.F.S., and S. Helkey, J. Bennett, M. Zumwalt, K. Cox, K. Garwood, M. Martinez, E. Ward, J. Lemon, M. Hill, A. Leonard, T. Bowlby, J. Scilla, K. Kinttle, and A. Meyers, Stevenson High School.

This form is in compliance with the intent of RCW 65.04.045 and prescribed by the Public Land Land Survey Office, Department of Natural Resources - 1/97

MARK THE CORNER LOCATION BELOW AND FILL IN THE CORNER CODE BLANK ON THE OTHER SIDE: For corners at the intersection of two lines, the corner code is the alphanumeric coordinate that corresponds to the appropriate intersection of lines.

For corners that are only on one line, the corner code is the line designation and the related line segment; i.e., a corner on line 5 between 'B' and "C" is designated BC-5.

For corners that are between lines, the corner code is both line segments; i.e., a corner in the SE1/4 of the SE1/4 of section 18 is designated MN 4-5.



RCW 58.09.060 (2) requires the following information on this form: an accurate description and location, in reference to the corner position, of all monuments and accessories (a) found at the corner and (b) placed or replaced at the corner; (c) basis of bearings used to describe or locate such monuments or accessories; and (d) corollary information that me, be helpful to relocate or identify the corner position.

ACE FOR ADDITIONAL COMMENT:

Found 21/2 " Aluminum pipe w/a 21/2" aluminum cap in mound of stones.

Sylvin Sylvin Sylvin Sylvin Bishop BT

Erila Erila

New BT 329

NORTH