T. N. TRANTOW SURVEYING

P.O. Box 287 Bingen, Washington 98605

LAND CORNER RECORD

1. History of Corner Establishment and Subsequent Restoration:

No record of previous establishment.

2. Description of Evidence Found:

No evidence of previous establishment.



3. Describe Monument, Accessories and Corollar. Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 30819 Page No. 36 Date of work January 26, 1982

Set a $1\frac{1}{4} \times 30^{11}$ galvanized iron pipe with $2\frac{1}{2}$ brass cap 22" in the ground, from which bear:

16" Douglas-fir, N46E, 14.25 ft. to nail in face scribed 1/16WT 22" Douglas-fir, S84W, 7.72 ft. to nail in face scribed 1/16WT

C = 30 E 1/16 1982

Both trees are marked with Longview Fibre Co. witness tags.

Washington Plane Coordinates: South Zone Y 143468.84 X 1657794.09 third Order Accuracy. Derived From: Skamania Co. control surveys, 1977

Pin Pointed on Photo No. 92-6 Date SW-74 Located at Trantow Surveying, Bingen

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 29 January 1982

7. Laws of 1973. Date 7 29 January 1982 15673 Strature Certificate No.



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at 12. 45 M. In Book of 2 at page 2 at the request of

TRANTOW SURVEYING

2/2 : 4 12) (16.6) 6 2 12.4 1 County Auditor /

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), c. r. 50, Laws of 1973.

ROLL 282.2.
DAILY RECORDINGS
BOARD OF COLINTY COMMISSIONERS
MARRIAGE APPLICATIONS