

INTERNATIONAL PAPER CO.

ENGINEERING OFFICE

P. O. BOX 67 - AMBOY, WASHINGTON 98601 - PHONE (206) 247-5411

1981 9/6 7A - 4

93077

LAND CORNER RECORD

Skamania

County

Z- 13

T 9 N, R 6E, W.M.

Corner Code No.

Segregated Surveys:

Name: Section Corner 33-34

Corner No.

DLG, IES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:



Corner established in 1903. Post and two BT's.

2. Description of Evidence Found:

Found 1" iron pipe and 10" "Larch" (Pacific silver fir) BT with visible scribe. BT is blown down. Could not find other BT. Origin of iron pipe is unknown.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. _____ Page No. _____ Date of work 8/81

Set 2" x 30" galvanized iron pipe with brass cap stamped:



Re-referenced as follows:

16" Silver fir stump BRS East 26.2', scribed "RP S34".

36" Hemlock BRS N54W 47.5' scribed "RP S33".

Distances to nail, RPs tagged.

Washington Plane Coordinates: N/A Zone, Y _____, X _____

Order Accuracy. Derived From: _____

Pin Pointed on Photo No. _____ Date _____ Located at _____

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date Sept 15, 1981

Frank M. Pumphrey
Signature

L.S. 15669

Certificate No.

93077

AUDITOR'S CERTIFICATE

Filed for record this 15th day of September, 1981 at 1:30 P. M.
In Book 910 of Documents at page 4 at the request
of John Hodder for International Paper Co

Joe Messenger, by B. Babcock
County Auditor
Rep.

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.